X . Iron rod inplace - fd by WHKS 1972 Survey #542904 (1)

1/4 corner 29-32 Hi Forest 104-15

6-1892. Chas Fraser p491 no 965 S28 Tom Kelly, Mich Donahue. in setting SW corner 28 - measured from S 1/4 28 (corner in bridge to SW corner 29 - 1½ miles short 4 lks ~~making each half mile 39.99 1/2~~ 40.18 2/3 - plat shows 39.93 1/2 for. west half of S line 28 evidently ~~error~~ OK ~~if shortage of 4 lks~~ correct. apparently no corner set at S 1/4 29.

See p389. S line 29 is 80.40 Ht - S line 28 79.90. Check carefully

1960 Minn Hwy Dept Rw Val.

found stone 2 feet deep, hub riser. 4 references all removed form area in county grading. County re referenced. before grading. B321 over)

6-7-1968 J Kerr placed 1/2" rod by Co reference.
added new reference.
Disc in power pole.
Cross in top curb
" " " "

LE ~~56.72~~ or 58.5
LW 55.61
NW 52.59

Meas corner above west to county P.I.
assumed to be SW cor 29 2642.02 — No Good

Co H D B 321. 1966 found 1/2 rod. could be from DeValo corner.
Meas east 2655.42

1903 R Fraser old fieldbook No 10 P19. L 29. Egbert Brink (?)
No disc & corner but sure used & checked corner. stone at
center 29 found and checked. Meas east claimed over. 35 1/4 L 23.26'
making 2663.26. way over actual. Could believe that much
for all L line 29. 5303.26 now. ?

High Forest 1/4 corner 29-32 #542904 | 2

Cont Mons Yr. by '853

40.00 set temp 1/4 steel post

West on true line between sect 29+32

40.10 set 3/4 steel post in mound 2° 50' E

of creek & sod. depressed channel

make trough 4 yds planted Orange

Orange steel W/S

10-26-94 FD 1/2" IRON IN GOOD SHAPE IN INTERSECTION CR #35 + CR #8.

7-5-96 FOUND 5/8" IRON ROD BY J.K. SET REF PIPE ON EAST EDGE 44TH AVE SW IN NE 1/4 SEC 32. ℄ 44TH AVE SW W 7 1/2'

℄ CR 8 + 35 NORTH 89'

7-5-96 Cont. T@ Ref Pipe

4RT P.K. In P.P. # 38532 (1st Pole North Of Corner on East Side CR # 8) To 1/4 Cor 29-32

347° 34' 06"

To 1/4 Cor 29-32 (5/8" Iron) Hor 89.39

7-8-96 Removed Iron.

10-25-96 CHD Set 1" SA Pipe W/Cap.