X 6-1-1971 set C1M over Fraser iron & 3/4" x 10" iron. ①
#543104

1/4 corner south 1/4 31 Hi Forest 105-14.
7-1897 H Fraser P608 no 553 S 31 Town Board.
could not find corner or any evidence or knowledge of it.
located corner M & L 39.93 (2635.38).

11-1905 Ch Armstrong P102 B S 31 ~~C.Z.K. Russell & Bleate?~~
has iron stake on plat as S 1/4 31 as set by H Fraser
on M & L line above.

12-1915 J Kerr P 242-5 B S 31. Reuse survey.
found no corner - run line from S 1/4 32 west to twp cor
set SE 31 unfound and temp point on line for S 1/4 31.
total line 7909.98 or 2636.66 - see P608 2635.38.

1-23-1938 J Kerr B 12 P 16. S 31 Mrs WE LAMP
found S ¼ 31. and old iron bar. set 1"x2' pipe over iron bar.
60 D in elm - SW 135.6. packed in
60 D in 4" elm NW. 92.6 small boulders.

Minn Hwy Dept. 60 D spike also Co H D B 290 P. last page
⅝" rod in center road.
spike in power pole NW. 43.95
" " tile " SW 95.0
Center line road east ?? 421.6 Co. H. D.

5-27-71 Co surv. used rod found in center road at above tie
and meas west to township corner. set bolt at 421.6
- as east end of line used C & M set over wagon skein at S 31-32
- continued line west on traverse from bolt at 421.6. - deflection
2° 46' 45" 1448.42 or N 70.21 W 1446.71 see Card 2.

#543104 (2)

Card # 2. S¼31 High Forest 10 5-16

Cont traverse deflection S 0° 55' 15" 770.66 or N 82.45

W 766.25 Making total ½ mile. 2634.56 John K. on 2636.66.

H Fraser 2635.38.

6-1-71. found 1" iron pipe as recorded by J Kerr. B12 P17. 9-6-1939

257' east and 20' south of S¼31 and limestone with cross as recorded 247.05 south. from there came back to ¾" iron at S¼31 and found. 1" x 22" pipe and many stones above 1" solid iron set by H Fraser in 1897. - this was.

6.25' North and 1.03 west of ¾" iron. Fraser iron down 3' set ¾" x 10" iron over Fraser iron with C / M above.

10-25-72 final west 2634.09 east 2634.05 (5-8-73 2633.78 Elect. Dist.

this mark 26 33.53 west to turn corner 11-8-71 Meas E to N'45 164-14. 2048.15' temp 36°
RP- big nail head 9/16" on SW side PP # 5991 up 4' NW 38.28.
— center metal tele box post ⊕ NE 34.05.
— 16 D on east side 24" red oak with bad scar
in root area on SW side tree nail up 4'+ 10' W of N 51.3
— Center N-S street (road) W. 55.0
— true section line east corner 17.22 north of 20' ⊕ pipe
— " " " " " 3.66 " of metal PK nail in edge of floor
— pushed line from point 20' north of 1" pipe 25' east over 1/4 corner just found & found 1/2" iron drift pin planted 421.6 west down over 4' - pin about .15' south of this line and .92 W of orig 421.6 or 422.5± - Came 10" N center road west 18" off road on N side - set round head iron bolt 1/2" x 12" ±
RP- Center near West Concrete SE 49.55 - Center tele pole up 4' No & SW 66.2

Card # 3 S 1/4 31 Hi Forest 1.05-14. (3)
#543104
5-8-73 Meas east to S 31-32 by elect meas.
Meas 2633.78 prior meas 2634.05'.
set 3/4" x 12" smooth round iron as PoT on hillock
back 281.24 to project line west for traverse purposes.
of
Took RPS to PoT for future use
40.63 NNE to cone nail in knot on E side PP# 5992 1' below keplet
100.85 ENE to Cone nail in knot on N side 6" ± cedar tree
up 3' taken meas level 1' ± slope down to RP.

7-10-78 Found head of CIM broken off and gone
Corner 6' N ℄.

7-10-78 Found head of CIM broken off and gone.
Also someone drove an iron alongside
the CIM
- The corner is 6' North of ℄ E-W road.

"543104" G

11-2-98 ✓ South ¼ Sec 31 T16N-R14W

Fnd. Cim down 0.8' w/head broken

Checked tie in P.P. S89°NW 38.10'

" Tele Cable Box NE 3.26