/ 6-15-71 found stone set 5/8" rod temp. 5-9-73 LFC/M (1)

1/4 corner West 1/4 31 Hi Forest 105-14. #543106

East 1/4 36 Rock Dell 105-15

11-1905 C Armstrong P102B L31 IK Russel.

Could not find corner, set boulder stone 10 x 12 x 15" with stake M & L. 39.70 (2620.2)

-1/16 south set stone 6x10x10 (check at court house for size. film not plain) M & L 19.85 between loop on monument & above 1/4 corner.

4-1906. Armstrong P 106-"B" L 36. H. L. Stiles.

found stone as placed P102 "B"

-1/16 south set stone M & L. (no mark)

-1/16 west set stake & stone M & L. 19.925' 1315.05'

(over)

1/16 Center SE 1/4 36 set stone intersections.

12- 14624-1915 J Kerr. Page 242 "B" L 31 John L Boyce attorney.
- found corner at 5256' west of E 1/4 31.
- No mine N & S or Tie.
- set property line south (still farm line) 1528.5 west of Center 31 as set or 1099.5' east of 1/4 corner found.

8-1950 unidentified info. Stake & stone 1-1969 Nat County
8" bur oak NW 11.0 - 10" bur oak W 7.0

6-1924 Boyce Co H D B 39 P 40
found corner stone no RPS run E-W 1/4 line
2433' west - then 11 32.63 then 1702 To stone W 1/4 36
see 1/4 35-36 Rock Dell. } P80 stone
RPS-tele pole SW 49.5 - cor P NW 30.0

Card # 2. W 1/4 31 High Forest 105-14. (2)
E 1/4 36 R Dell 105-15.
#543106

5-26-71 Co surv. set nail in line fence south on S edge road. used rod at W 30-31 as temp corner (assumed rod).
- Meas. 2653.0 R 2620.2 M & L ch Armstrong 11-1905.
- using these 2 points cont line to bkrp cor S W 31. found same at. 5279.25. line fell. 14.6 west of corner (corrected).
6-14 found W 30-31. 3.2' W and 3.47. S of 00 rod.
on calculation dug for W 1/4 31 found stone, stake and iron 13.08 north and 6.3 E of 2653 nail
corner not midway or on line either. .6' east of direct line 1.51 south of midway.
Meas to stones. N 2636.45 S 2633.43 ~~E to C/M set 2599.85~~ R 2603.7
(R 2620.2)
~~W 30-31 east to 1/4 cor 31.~~

Corner lies 2' N center E-W roads
5½' E center road north - line fence & W 6'
⅜"x28" rod up 2" under new 5 bart fence south 6' W & S 90.0
~~pipe cap N E side tele cable pole~~ Gone 5-9-73. ~~Cable on W side.~~ SE 57.77
- fence line running W & S side road S 39½ W
11-1971 Danger Cable & Telephone now diagonal across road. very near in line fence south - stupid telephone

5-9-73. found iron set C I M. on stone as no room for riser. tele cable pole R P gone completely. New R P. 41.82. & W to S E rounded corner tele cable box post 5 1 6.