/ 5-9-1973 set 3/4" x 4' pipe as perm corner. (1)
corr 4-18-75

105-14

1/4 Corner 31-32 7Ni 7 East ~~15~~

4-1884 Hunter P388 no 379 S 31 21E Mayo. #543206

B trees gone, found stake and pole standing by corner of fence (rail) running east & south anered by SW Russ and others as where orig stake stood accepted as corner.

- meas north 39.87 which is 1/3 distance to NE Cor 30 a stone found and set P177.
- meas west 10.07 1/2 chs then 90 lks then 2932 1/2 to center 31 a stone set by Freeman in 1857
this 90 link width runs north 33.25 where it forms road laid out this survey at PI

over)

12-1915 J Kerr P242B
Runs from SE cor 31 as established north to NE 31 stone found
set 1/4 31-32 M&L 2635.9.
— ran west to W 1/4 31 5256' could not find stone at Center
31 set stake at 2628.0 M&L not entirely correct.
and intersect the mean with 1/3 mean from S 1/4 31 and Center 30
of 2634.3 each 1/3. not best way to set center corner.
but if E-W-S lines of Sec 31 are M&L gobe and N gone
could set a guickie. (Co Hwy Dept has referenced P I on P.O.T.
at Center 31

5-8-73 projected line from 1/4 29-30 south over
29-30-31-32 C/M&L to P.O.T at 2624.19
Cont line south to flooded creek bank 2471.19
Offset left to computed line to true M&L point
at 2625.99' North and south 2625.99

#543206 (2)

Card #2. 1/4 31-32. High Forest 10 5-14.
5-9. searched by digging and probing. in corner
area N & S come as J Kerr 1915 meas of N & L.
J Kerr meas 2635.9 or 5271.8
Computed mean 5251.98 or 2625.99 Medway.
set 3/4" x 4' pipe up 16" as corner with elec fence post
on S side and farm fence post on N side
Corner in worst possible flood plane with washed out
high water channels east and south.
Corner under what fence to left
82.0 6' N & E to 60 D S side leaning 16" box elder.
Note Kasaler may have measurement west.

Govt Notes Yr by -053
40.00 Set 1/4 Set Post
Bur Oak 12 in N 30 W 210 1K5
Bur Oak 10 in N 51 E 313