5-22-71 Set C.I.M. over 5/8"x 18" rod Card # 1

#543304

1/4 corner south 1/4 33 Hi Forest 105-14.

4-1875 Hunter P271 no 269 S.3 L.Y. Fish
used NW cor 3 - mentioned that S 1/4 33 "M" did not set any corner at the 1/4 past. may or may not have been a corner there. refered description of NW cor 3 to P 343 no 337 also W 1/4 3 which was controversy.

10-1904 C Armstrong P94B S33 A Tabbs, L Albright J Brink T Kelly, A Ringley.
found limestone at corner.
used only to set center S 33.

over.

1940 Co Hwy Dept.

cedar stake mon. stone monument. two rivets North sec 3-4 104-14.

Hub N 70.88 - Hub L 68.67.

NE cor Conc cor post L 38.25'

(these ties identical to ties of N ¼ cor sec 3 just west.

of L ¼ 33 - (same deal at N ¼ 4 & L 32-33)

5-22-75 Set C.I.M. over ⅝" x 13" rod on line from S. 32-33 over N 3-4 (104-14) and midway between S. 32-33 and S 33-34. Corner lies in Co. Rd 6 5½ N ℄ and 12' E ℄ Field drive N

R.P.'s: Punch hole top center E. end Field drive culvert N. 18.42'
Punch hole top center W. end Field drive culvert NW 30.01
C.S.O in S. side pole # 11048 NE 103.35'

#543304 Card # 2

1/4 Corner South 1/4 33 Hi Forest 105-14

Set pipes on (west) Property line of (County Park Property) at

27.5' North of C.I.M. - Pipe
162.65 north of C.I.M. - wood stake
287.0' north of C.I.M. Pipe
Bank of river falls 302' north of C.I.M.

R.P.'s to Pipe 287.0' north of C.I.M.
Co. surv. Disc & spike So. side 18" boxelder E. 28.49
Co. surv. Disc & spike N.E. side 30" Elm S.E. 18.65

Set 1¼" x 18" pipe on East line of County Park Property 26.04' North of R.R. Spike set as property Corner

Pipe Falls 5' south of River bank