7-27-1974 Set a C.I.M. over the Stone
#543305 (1)

section corner south 32-33 Hi Forest
5-1878 Hunter P343 no 337 L 4 105-14
Corner missing. To reset corner — HD Morse & others.
meas from S 1/4 32 to S E cor 33 119.90 chs short
10 lks from recorded govt meas.
set stone 7 x 8 x 21 at above corner. at 1/3 dist. 39.96 2/3
and on meas from line betw sections 32-33 north.
bringing corner in middle of road agreed by Walter who cares
for 8 lines on Morse farm as where orig stake stood
when he built road fences.
~~He will set stone~~ no meas to N 1/4 4 set. N & L
orig record not given at this correction point

10-1904 C Armstrong P 94 B & 33 A Tubbs, L Albright
J Brix, T Kelly N Ringley

found limestone in road set by Hunter,
33' south of row of trees running east and about 6' west
of fence running north.
- mens west 2639'
- mens north 2634.75' to temp point in field

Co Hwy Dept completing notes - stone with 3/4" rebar and
found nothing set N & L on range line (down by bridge.
same line to Rod on N "44" error somewhere. N "44".

#543305 (2)

Section Corner South 32-33 105-14 High Forest

7-27-1974

Dug with the backhoe + found a portion of the recorded 7x8x21 stone leaning to the EAST. Dug around the remaining 7x8x15" and found nothing. Straightened the stone - drove a 3/4" x 3' iron on the south side + set a B.I.M. over the stone flush with the bit. on C.R. #6.

R.P.'s

Punch hole in W end 18" C.M.P. (Field drive) N. 24.57

C.S.D. S.W side P.P. # 11038 N.W. 106.5

10-26-94 FD CIM IN GOOD SHAPE IN BLACKTOP CR #6