X

#543506 (1)

1/4 Corner 34-35 Hi Forest 105-14.

? No courthouse records. (over)

Minn Hwy Dept const notes. Sta 2646.8.

- 6"x10" limestone inplace, line fence south.

Center line highway as graded lies 9.6' south of corner.

- meas east to center 35 station 2643.2.

7-1930 Co H D B57 P39

found old oak stake 18" deep in good condition. Plat meas 1318.7 south of 1/16 corner north. - corner lies 8.6' south of PI of road survey. Meas east 2642.55

records from armstrong plat of Stewartville (over

Meas west to 1/16 corner as plat 1323.5'

6-1892 T Fraser P488 no 413 S 34 Stewart Moss.
all evidence of corner gone - reset large boulder with cross
with stake under edge on N-S section line intersected by
E-W 1/4 line W 1/4 over Center.
- set stone with cross at intersect lines as Center NE 1/4 34.
-16 north set boulder M&L 19.99½ (1319.34'

4-1909 Ch Armstrong P 316B could not find boulder run line from
center 34 over 1/16 stone found. doubled 1323 and set limestone .6x10x30.
with cross. this fell on line N&S fences and 21' south of cor fence.
-16 north found boulder above at 1318.0
used fence corner as 1/16 center NE 1/4 set stone 496.2.

See Card # 2

#5435016 (2)

Card # 2 1/4 34-35 Hi Forest 105-14.

Center highway 30 accepted by McGhie & Betts as line N&S and fence N&S as line E&W.

Armstrong near center manhole to stone reset as corner 2646.

Munn H D near " " " " found 2646.8

4-30-1970 dug for stones along highway in Stewartville for help in N-S line dug at SW Bonners Lot and NW Morse & Sheets Lot found neither. used iron & stone at corner of block across from church. Line did prove near center set nail on this line at 2646.8 lines fence north fairly well.

- set offset 170' west at SE 34 and corner set (nail) as E 1/4 34. line north (recorded straight) came 1.24' west of rod set at

over

NE 34 by McGhie. set ½" pipe as 1/16 at 170' from offset (this line between McGhee rod and ¼ cor not true line (a kink) dug massive hole at 1/16 for recorded stone set 1892. T Fraser P487 very wet, many large boulders & iron wheel rim deep. corner gone. 1/16 corner could be set .93' west to straighten line would be better.

Gate N-E-S Gate by 1553

46.00 Set ½ Set post

Bur Oak -12 - 5-9 E 528 IR

Bur Oak -18 - S 76 W 592 IR

3-5-92 Yaggy-Colby found 3/4" rod 0.3' below Surface of Road. as Set by Co. Surv. in 1970 (see Cert on File For Ties).