1 8-25-71 set Auto axle with gear as corner. ①
#543605
section corner south 35-36 High Forest 105-14
5-1902 H Fraser P16B L1 104-14- cors on south
line sec 34-35-36. 105-14 J Beach, R Sutton, J McBride
corner lost, set stone 7x8x24 on line & SW cor
35 over North ¼ sec 1. and Midway 40.00 between
L¼ 35 & L¼ 36.
- Meas west to N¼ 1 3.43 [226.38 a stone 8x8x22

12-1910 Ch Larson P144B L35 John Beach
found stone 7x8x24
- Meas west 40.00 to stake found set by Fraser

7-1930 Co HD B 57 P 41 found boulder.
just south of corner fence post on west side of road.
- meas west to drag tooth 2644.5
- meas north 5280.6 to fence corner. as 25-26-35-36
as accepted corner for 50 years aved by Robert Stamer.

8-25-71 co surv. found N 1/4 1 10 4-14 and 1/16 stone west
used line from S 34-35 over C/M at N 1/4 1 projected
east recorded distance of 3.43 chs 226.38 and set
car axle with gear as corner on this line and meas
- corner came in center bottom of ditch on west side
of N-S road. dead-ending in farm 80 rods south.
- PP staff and gear as set. in bottom ditch in line fe E-W
19.5 just S of W to Fence Cap on S side 3 phase PP
9.3 NW to Dade R bear cap on NE side regular PP # 15356
see card #2.

Card # 2. S 35-36 High Forest 105-14. (2)

summary final meas from corner as set. #543605

226.38 west to C/M at N 1/4 1 104-14. 104-14.

1597.84 west to 1/16 stone found M&L 1371.46 N 1/4 & N 1-2

2640.2 west to C/M at S 1/4 35 105-14

26.0 ± east to center N-S road.

1137.27 east to 1/16 stone found. betw N 1/4 1 and twp cor.

2641.81 north to C/M at 1/4 35-36 set M&L. To angle steel corner post set in concrete as. 25-26-35-36

5-16-95 Fd Auto Axle with gear in good condition in Road ditch. Set post & sign 1' south.

FD 1/16