4-26-79 Set a B.I.M. over a ½" x 17" rod. #550104

¼ Corner 1-12
Set Michael Kerick 5-1854 Rock Dell 105-15.
4-1876 Hunter P291 no 286 L1 Knut Larson.

Corner could not be found, B trees gone completely,
Meas South line sec 1 carefully 80.13 set temp point
Midway only while setting center, did not retain point.
2E1 a stake in mound undisputed
2W1 a remains of old fence post claimed set by side of orig stake

4-26-74. Set this corner by lost methods. M.L.
Total mile = 5274.20. E½ = 2637.10. W½ = 2637.10.
and by elec. traverse.
Cor. falls. 9.5' West N.-S. fc — 60. N. fc. running East.
R.P.'s
24" OAK (center) South. (slope) 61.5'

~~Beattie~~ set Michael Kerrick 5.1854

37.40 Creek 5 lks wide runs North

40.00 set quarter section post
Burr oak 11 N 70 W 4 16
" " 9 N 25 E 9 7