#550205

X 7-22-71 set CIM over pipe and orig L stone. (1)
section corner. 2-3-10-11 Rock Dell 105-15.
6-1898 H Fraser P520 No 486 Ll H. Skjerner
found stone set in center of roads, tested by
L.W.B.T. still standing and found corner correct.
- meas south 39.91½. (2634.39 to stone 3x12x20
set M & L.

1939. Co H. Dept. found L stone with stake on
North side B99 P9.
Lp F.P. NE 77.0 Lp F.P. SE 82.7
Cross N headwall culv NE 21.95, S headwall S.E. 20.4
meas west 5272.7

over.

12-1949. J Kerr B44 P42. found stone set 1" pipe riser, Lp PP S.E. 47.0, Lp FeP NE 61.3.

7-22-71 dug by hand, found 60 ⊖ down 3", hub down 8" 1" pipe down 18", Top recorded L stone down 4' stake N side.
- reset 1" pipe in stake hole, bending to center over L stone. with CIM over pipe and stone.
- meas south to stone found (reset by J Kerr 1949). 2633.15 then 2634.3 to 10-11-14-15 R 2634.4 M & L
¼ corner found .14 west direct line. .54 N of midway. RP 2-3-10-11. corner in center tee road intersection.
29.0 NE to top center N edge of N end 30" field drive culv.
31.2 SE to rivet top center S end 30" field drive culv.
54.15 SE to center of bottom of massive power control switch.
217.7 WSW to hard nail in knot N side PP 44294 mast lever.

#550205 (2)

Section Corner 2, 3, 10 & 11 Rock Dell 105-15

Set by Michael Karrick 5-1854

70.00 Enter Barrons bear West

80.00 Set post for corner to Sections 2, 3, 10 & 11
Burr Oak 18 S 77E 589
Dug trench.

Nov. 1857 John Fellows Pg. 42 No. 64 show sec. Cor.
1/16 west 19.77 Chs. M&L to 1/4 Post

(See Survey for Interior breakdown of Sec. 10