10-27-75 Set CIM

1/4 Cor 2-3 Rock Dell #550206 105-15 (1)

10-21-75 Dug 6 1/3' x 8' x 9' deep with backhoe on line between section corners and at prorated Govt measure. Found nothing. Corner in river bottom area. Dug hole 8' deep and still over much silt.

10-27-75 Set CIM over 5/8" x 18" rod on line between section corners and at prorated Govt measure. Corner 6' W & N-S road; 16' S & road E; and 36' S Fence E.

RP's: Punch hole top N end CMP to road E NE 37.29
" " " S " " " " " E 25.57
CSD W side pp # 19160 SE 73.24

∴ NE corner of bridge (low) SSE 204.2

∴ NW corner of bridge (low) S 203.2

(1/16 S) 10-22-75 Dug 6⅓' x 8' x 5' deep on line between section corners and midway between between 2-3-10-11 and comp. ¼ Cor 2-3 to clay. Dug from line of fence (East) and North. Found nothing.

(1/16 N) 10-22-75 Dug 6⅓' x 8' x 5' deep to clay. Found 5" of wood (piece) running vertically into clay - possible stake. Point came 3' W of ℄ and 1.7' S of S. lane fence ℄ and .43' E of line between section corners.

(2)

1/4 Cor 2-3 Rock Dell #550206 105-15

Set by Michael Kerrick 5-1854
North on random
32.80 Creek 35 lks wide runs East
South 4' E on true line
39.75 Set quarter section post

Butr oak 18 N 40W 69

" " 15 S 53 E 81