/ 10-27-75 CIM set #550304 (1)

1/4 corner 3-10 Rock Dell 105-15.
11-1857 J Fellows. P42 no 64 & 10.

used corner.
set 1/16 corners - east & west 19.77 ← no meas. given in W. Dhalf
south - south 19.76 (M&L print faint check C House book

(corner likely a lost corner indication could be set M & L without too much error).

Pat's note

10-20-75 Dug 13/5 x 9 at corner location (covered M&L and line of fence N) Found old road work to clay with clean clay on bedrock 18" deep. Found nothing. (over)

RP's to traverse nail Nail SW 7.64; Nail NW 7.65

10-22-75 Dug again using line from Sec. Cor 3-4-9-10 over stake found at 1/16 W of 1/16 Dug S. side of road near edge. Found nothing. Road cut sharply on this side.

10-27-75 Set CIM over ½" x 10" rod at double the line and measure from Sec. Cor 3-4-9-10 over 1/16 E. of (The Sec. Cor.) (found) as per Fellows survey Corner in line of fence N and 8' S ℄ E-W road.

R.P.'s Punch hole E end CMP to Field drive S. SW 20.02

Punch hole E end CMP to Field drive N NW 35.05

#550304 (2)

1/4 Corner 3-10 Rock Dell 105-15

10-21-75 (1/16W) Dug in line of fence S and tree line N. Found wood stake 4' deep in black soil and running into clay. Set piece of glass and golf ball over stake. Stake 4' S of ℄ and in line of fence So

Set 3/4" x 18" pipe at surface

R.P.'s: Punch mark top N. end 24" CMP to driveway N NE 51.50

CSO W. side pp #6735 SW 35.15

Center large Oak N 39.0'

10-21-75 Dug 10½' x 9' in line of N. Corner line between section corners and 3½' S of line as at 1/16 W of 1/4 Cor 3-10. Dug 2' deep to clay.

set by Michael Karnick - 5-1854
west on true line between Sections 3 & 10
40.00 set quarter Section post
Burr Oak 9 S9E 38
" " 7 N74W 280

9-12-84, 1/4 Cor 3-10: Found CIM knocked over.
Reset over 1/2" re-rod below. R.P's checked OK