NEEDS MON. WILL USE PIPE LOCATION #550504 (1)

1/4 corner 5-8 Rock Dell 105-15.

No records.

1963 Co Hwy Dept B 266. assumed corner. 3/4" rod

Disc fence post N.E. 38.66.

Top of steel " " S.E. 59.44

Disc " " S. 48.22.

Hubs - NE 19.4 - N 70.0 - NW 78.27

Meas west 2652.33.

east 2643.07

Set by Michael Karrick 5-1854
40.00 set quarter section post
Burr Oak 10 S 35 E 36.5
" " 8 N 63 E 30.3'

3-23-77 Dug down 15" to 3/4" C.H.D. rod. Set a 1/2" x 15" pipe over the rod. Corner in ℄ E-W road and 2' East of line of fence South R.P.'s CSD in pp # 6449 SE 102.05'
Pencil mark in top lug nut E end of 16" CMP in field drive to South SSW 42.47
Pencil mark top lug nut W end 16" C.M.P. in field drive to North NW 102.45'
Not ready For CIM

8-23-84, 1/4 Cor 5-8: Dug down with backhoe on South side of pipe set over iron (removed both) in 1977 to check conditions since road cut on

#550504 (2)

1/4 Cor 5-8, Rock Dell, 105-15

8-23-84 continued: North side and filled on South side. Found rock fill to bedrock ledge 4' deep at east end of hole (4' East of pipe) and 6' deep at West end of hole. No conditions at all in center of road surface.

L.R.P. Pipe { So. 9.56 / E 9.60

1991-1992 Using pipe locations for corner

(550504)

(17)

5-26-99
MW, MC, RF

1/4 Cor 5-8 105-15 Rock Dell
Set Ref pipe on west edge
Field drive 37' South of
℄ CR26 S.W of 1/4 Cor P.K. nail

TC Ref pipe
ART P.K. nail in PP# 6450 (1st pole
west on south side CR #26)
to 1/4 Cor 5-8

131° 46' 22"	132° 19' 26"
0° 01' 28"	0° 34' 34"
131° 44' 54"	131° 44' 52"

To 1/4 Cor 5-8 (P.K. nail)
VA 85° 20' 36"
Slope 47.875 Hor 47.72

T @ PI (5/8" Iron Int CR3 & CR26
ART PK in P.P # 6062 @ Rock Dell shop
to PK in PP # 48519 @ Rock Dell meats

172° 25' 16"	173° 38' 34"
0° 01' 32"	1° 14' 56"
172° 23' 44"	172° 23' 38"

186.63, 66.00, 49.50, 78.05 380.18

NATIONAL POINTFINDER NO. 447