/ 10-15-73 set C/M over recorded stone. 4 iron ①
#550905
section corner 8-9-16-17 Rock Dell 105-15
Cor 13-10-75
6-1875 Hunter P280 no 277 Lg. Peter Hoganson.
found stake standing anered by a mr. Ole Olson etal.
Wing and other settler as true corner seen for many years. All
3 B trees did not agree so accepted stake as is
-1/16 east set stake M & L 19.94½ (1316.37' S 88° 55' W.
- north set stake on line 26.00 (1716.0' N 35' W.
Hunter: N65E 1.43 RO 18"; S83½E 60 RO SSTW 17 (Stump) } Trees would any don't here now? Could

6-1895 H Fraser P579 no 529 Lg. Marcus Wing, etal
found stake set by Hunter P280 with mea to 1/16 east of
19.94½ the same but B tree distances did not agree as Hunter
put them down. Mr Wing avers both section corner stake
and 1/16 stake east were Hunters stakes over)

planted limestone with cross in place of stake as found
1/16 west set boulder M & L 19.92 1/2. (13 15.05)
- meas south 39.90
(this corner in deep fill in black top county road, county never
had corner. must be replaced from west from 1/4 cor over 1/16 cor.
ratio of chainage expected - west half of north line 17 as follows
record 2643.63' - actual between stones found 2642.44'
about 1.2' in half mile less than record - 1/16 corner in good area to find
(County may have rod in road assumed.)
RP 1935 B 19 P 9 No deed cors. Sta 240 + 78.0 20° 22' Rt
Meas south 5280.2

#550905

Card # 2. 8-9-16-17. Rock Dell 105-15 (2)

10-15-1973 ran aerial from C1M at 7-8-17-18 over C1M at 1/4 8-17 east to center Co road #3.
Meas elect from 1/4 8-17 2631.29 R.WF1895 (2630.1
Meas elect from nail at fence line 1/4 16-17 2657. ±
R 39.90 (2633.4
dug and found recorded limestone down 18" 24.63 south of nail or 2632.4 ± to fences E & W at 1/4 16-17.
- drove iron pipe or rod on east side of stone with C1M on top flush with road surface.
corner came. 24.7' south of line projected from west corner came 11.0 south and 2.1 west of County nail.

over

final meas west 2629.2 (ac stone fell 24.7 south of projected line from west and only eye line arrived at above final meas it could be + or - above amount.

R.P.

57.8 NW to Co Hwy disc on NE side PP # 6087.

47.74 SW to Co Hwy disc on NW side PP # 6103.

2' west Center N-S road near Ledge road west.

ac 1/4 16-17 not found after extensive digging

No accurate meas south. Non 2632.4 to fence east line

R WF 6-1895 - 39.90 2633.4

Set Michael Kerrick 5-1854

66.10 Creek 6 lks wide runs NE.

80.00 Set post for corners to sections 8, 9, 16 & 17 { Burroak 10 S 15 W 298 / Dug trench

#550905 (3)

Section Corner 8-9-16-17 Rock Dell 105-15

5-28-85, T.H. Prop. Cor. 22 chs. (1452.00) North of Sec. Cor. 8-9-16-17: Set nail on line between section corners and 1456.40 North of Sec. Cor 8-9-16-17 (PH. 264' = 4chs south of fence E on North line of 12 acre which I believe is also a property line surveyed by Hunter) Dug only a small hole to check conditions. Found Fill to hard packed green clay at and 2' deep. No chance for corner.

5-28-85, Section Cor. 8-9-16-17: Dug from a point 3' North of the CIM, North for 8', West 1½', and East 2½'. The South edge of the hole joined Rogers old dig. The NE area of the hole had been dug by someone, probably the CHD — Their

diggings extended even farther East and North. A few inches West of the West edge the the (CHD) dug area, found 2" diameter hole at the clay line, filled with wood piece and running down 2"+.