6-14-85 & CTM. #550906 (1)

1/4 Corner 8 - 9 Rock Dell 105-15
6-18 85 Hunter P280 no 277 L9 Peter Hoganson
Ole Olson etal.
1/4 stake gone; reset stake by distances from 2 BT stumps with marks still on stumps. bearings did not quite agree so used distances only.
— 1/16 east set stake N 8 L 19.98
— south set stake on line at 924 14 chs then another 4 chs 14 chs 1452 22 chs to LW 9. (South 52 acres still on record or point 14 chs south. corner in black top road. impossible to find, hard to reset)

Set by Michael Karrick 5-1854
40.00 Set quarter section post { white Oak 10 N 87 W 100
" " 12 N 45 E 62
65.70 Creek 6 lks wide runs NW
74.70 Same runs NE.
78.40 Same runs N.W.

5-20-1985, 1/4 Cor 8-9: Set nail on line between CIM @ Sec. Cor 8-9-16-17 and CIM @ Sec Cor. 4-5-8-9. and 2640 from 8-9-16-17 (T. Hunter's meas.) Dug from a point 1' West of the nail for 4' West, 3' South, and 11' North by 5' deep to clay. There was a road down 1' and another dark 3'+, then sand to clay. There was about 1" of greenish clay before the yellow clay. The road is in appx 4½' West of the straight line between the section corners. Digging E-W to cover doubling distance from N-S 1/4 line set 9 on the N-S Fence at the 1/16 West and also a N-S road. Digging N-S to cover 2640 From South, line from Fence @ E 1/4 9 to Fence at Corner 9, and also fence West @ 1/4 Cor 8-9 (now gone - used CMO Cotton).

#550906 (2)

1/4 Corner 8-9 Rock Dell 105-15

5-20-1985 cont.: and also T.H. measure (14 chs) N. from property fence running east. See Drwg 23-105-15-2 for location of different positions.

5-21-85, 1/16 East: Found Leonard Sandstone pipe & cap standing 1/2' East of N-S fence. Dug from pipe South for 7'+, North 2', East 1 1/2', and West 1 1/2'. Could find no evidence of Hunter stake

5-22-85, T.H. prop. cor. 14 chs So. of the 1/16 East of 1/4 Cor 8-9: Found corner post (in ground) to fence West and South 1 fence Note on ground. Dug 4' diameter around spot post stood. Mark ran deep into clay. Found nothing further except small dug area on N. side of post that could have been where prev. post stood.

6-14-85, ¼ Cor 8-9 : Set a CIM over a ¾" pipe as the corner on line from the E¼ Cor 9 (set this survey) over the Sandstone pipe found at the 1/16 West of the Center 9 and at the double the measure from N-S ¼ line over said Sandstone pipe
Corner .8 East of ℄ C.R. 3 and 16½' South of ℄ driveway running West.

RP's : C.S.D. in NE side pp# 6079 NW 50.28
Punch + in top South end CMP in driveway WNW 33.72
C.S.D. in NW side cut off pole with telephone by SW 75.65