/ 6-14-85 : CIM #551006 (1)

1/4 corner 9 - 10 Rock Dell 105-15

11-1857 J Fellows. P92 no 64 ? D.B. L10
used corner. set 1/16 east 19.72 19.92 and center (faint print see record

---

6-1875 Hunter P280 no 277 L9 Peter Hoganson
Ole Olesen etal.
D.B. West in 1875
found orig stake standing in range of fence (likely east)
B tree so far away didn't look for to find corner (common west)
-1/16 west set stake M & L 19.98 1/2 to center stake.

7-1966 J Kerr run straight line for grading road between section stones - Culvert near 1/4 cor very near centerline. (corner)

if corner ever required could be set N & L without much if any error. as long as it was in range with fence east reasonably.

40.00 set quarter section post } Burr Oak 15 S 80 E 9/6
Set by Michael Karrick 5-1854 Dug trench

9-19-84, 1/4 Cor 9-10: Dug from the t.n. (set in ℄ N-S road and in ⊙ line with fe. East) for 8' West, 4' North, 4' East, and 5' South by 4½' deep to clay. Condition very poor. Clay and black dirt mixed at clay line. t.n. } NW 11.65 NE 12.78

9-19-84, 1/16 West: Dug from t.n. (½' N. of c.p. to fence E-W-S) North for 5', East 1½', and West 1½'. Found pile of stone 2½' North of t.n. Found old post stub 1.8 N and .9 E. of t.n. found possible old stone mark on NE side of post stub and 2.8 N & 1.8 E of t.n.

#551006 (2)

¼ Cor. 9-10 Rock Dell 105-15

6-14-85, ¼ Cor 9-10: Set 20" CIM over 5/8" re-rod as corner. Corner set in line with fence East (as per T. Hunter survey) and at double the measure from the N-S ¼ line Sec. 9. over the fence South @ the 1/16 East of the Center 9 (surveyed by Hunter). Corner comes in the center of the N-S road.

R.P.'s:

CSD in NW side pp # 6747 SW 67.69
CSD in N side c.p. = 44.20
punched cross in top N. end driveway
C.M.P. NW 29.63