/ 5-25-72 County assumed corner, references.
4-24-74 SET C.I.M. OVER ½" x 6" Rod
#551205 CARD # 1

section corner 11-12-13-14 Rock Dell 105-15

3-1858 John Fellows P51 no 74 S13-14.

said corner

- meas east 39.82 to S¼ then 40.24 to S E 12.
- 1/16 south 20.01 M & L or 2641.32 for ½ mile.

9-1913 D Williams. P228B S12 T Hansen, C Boehm

could find no evidence of knowledge of corner,
a point in center of E-W road 33' east of fence running
N & S on west side of road made a mean of 5280 from
corner set on town line for S E 12. which could have
been near correct corner. ditto setting S¼ 12 midway was
incorrect according to P51.

over)

1960 Co Hwy Dept B 2428 Assumed corner.

Disc top cor fence post — NW gone ~~54.85~~

" power pole — NE 53.5

" tele pole. — SW gone ~~59.45~~

Hub — NE 93.85

" — SE gone ~~94.96~~

Sta 262+45.25 PI Δ 0° 2½' lt from S.

Meas south 264275'

5-25-72 no corner evident found disc in PP & Hub NE. not gone

Center of top of tele dome just on RW to road NNE 115.55

" " corner " post " on RW to road ESE ~~59.45~~ NW 73.3

May as well accept corner as is - meas south close.

Meas West 5-25-1972 52 72.8 set ¼ 11-14 M&L. 2636.4

#551205 CARD # 2

SECTION CORNER 11-12-13-14 ROCK DELL 105-15

4-24-74.

Set a C.I.M. in the location of the the nail that was in place in the ℄ of the road. Corner lies in center E.W. road + ℄ C.R. # 15

R.P's

Co. Hwy. dept. disc. SE side P.P. # 6959	N.E.	53.52
Punch hole top lug clamp 18" C.M.P.	S.E.	89.77
Co Surv. disc. top. 6" cedar cor. post.	N.W.	59.8'

Set by Michael Kerrick 5-1854

80.00 Set post for corner to Sections 11, 12, 13 & 14

Burr Oak 15" S 34 W 1070

Dug Tronch.

6-28-96 FOUND CIM IN GOOD CONDITION. SET REF PIPE ON NORTH SHOULDER 80TH ST SW EAST OF CR #15. REF PIPE IS 11' ~~SOUTH~~ NORTH OF ℄ 80TH ST.

T@ REF PIPE

&RT P.K. NAIL IN PP # 6958 (1ST PP WEST OF CR 15 ON NORTH SIDE 80TH ST) TO SEC COR 11-12-13-14

350° 03' 07"

TO SEC COR HOR 93.00

7-3-96 REMOVED CIM

10-24-96 CHD SET 1" SQ PIPE W/CAP.