X 10-25-93 set RR spike in Bldg as final corner (1)

section corner 13-14-23-24. Rock Dell 105-15
4-1878 Hunter P 334 no 328 S 23. Hans Amundson
corner gone but in digging found where old E & Schon.
corner post had been ~~t~~ lowered to be beside org stake
before road laid out. set stone 4x7x16 with
broken stones around bottom of ston. #551305
- meas west 39.86 to stone set in place remains old post
- meas south 40 05½ to stake set in Center road replaced
by stone 6x12x24.

---

plat of 23 & 24 Armstrong show stone size as 4x7x16.

4-1878 Hunter P 335 no 329 S 24 Hans Amundsen
found stone P 334 as corner. clad
over)

1/16 south set stake (temp) M & L. 20.02 3/4

1/16 east set marked stake M & L 20.02 1/4.

1/16 center NW 1/4 24 set stake inters lines.

Minn State Hwy const notes

Station 2637+45.8 to ℄ twsp roads N & S.

making 2634.0 west to station at 1/4 14-23.

℄ state hwy 30 lies 46.2 (probably changed — new alignment (5.9'50 of old) north section line as built either found stone or assumed ℄ road as corner.

6-1963 J Kerr survey Sec 14 used state notes as to north & south ℄ east end section line set northing.

set by Michael Kerrick 5-1854

80.00 set post for corner to sections 13, 14, 23&24 erected mound with trench, pits, charred stake and Osage Orange seeds at each angle

Card # 2 13-14-23-24 Rock Dell 105-15 (2)

5-21-71 Co surv found 15' E lath used by state as placed hard nail 15' west as .00 for line to meas south. # 551305

Came 37.7 south Center 30 - 44.6 S E to old drive PP # 7010.

47.0 S # To pipe on S E side PP # 7011.

- found properly line fence running east at 1314.5 R 1321.81
- found good properly line fences E & W at 2644.65 R 2643.62
- set 40 D nail in line fence W. at 30' west main fence north.

- meas east from referenced point 12.4 south of 1/4 30 and in line PK at Center & road south 5285.0 R 5285.92
- 1/4 fence south to Center 24 found at 2649.2 R midway 2642.97
- evidently after fence leaves center 24 it surges west some 6'.

March, 1858 John Fellows Pg 51 No. 74 shows sec Cor.
1/16 East 19.96 Chs., 1/16 West 19.87 Chs. (see Survey For tree taken)

10-25-73 nail set as .00 as random corner.
of 13-14-23-24 R Dell, for final setting mear
1/4 23-24 south for proportional mear to set corner.
- found at 2638.66 R 2638.66
- found 1/4 23-24 N to 00 nail 2645.16 R 2643.63
- react 13-14-23 24 at 2643.63 or 1.23 south of nail
and 2.44 west of nail set RR spike in black top.
- did not dig as deep set culvert runs E-W directly below.
45.22 SE to old disc in SW side PP # 70 10
44.6 SW to bottle cap on SE side PP # 70 11 44.31
40' ± N to ℄ Hwy 30.
29.41 W to punch hole W end culv flange
23.0 E " E " "
mean E 5286.11 W 5264.99

SECTION CORNER 13-14-23-24 ROCK DELL (3)
9/27/88 FOUND 1/2" ROD, NO R.R. SPIKE, ROD 105-15
FIT TIES

#551305