10-18-73 set C/M. over 1" x 20" drill rod over stone (1)
cert 3-10-75
#551405
section corner 14-15-22-23 Rock Dell 105-15
4-1878 Hunter P 334 No 328 L23 Hans Amundsen
E.C Schon.
found boulder stone planted in center of road.
aneed by old settlers to be where Ld orig corner stood.
set another boulder 5 x 8 x 20 in its place.
– meas south 40.01. 2640.66
– meas east 39.91 to boulder 8 x 12 x 24 set in place stake.
2634.06

---

plat in Armstrong book place stone size as 4 x 7 x 16.

Minn Hwy Dept corner notes
Station 210+85.3 to ℄ twsp road N & S.
making 2634.3 west to station at 1/4. 15-22 over)

PI lies west 185.3. Tangent 446.7.
℄ state 30 as built lies 53.6 north of accepted section line, either found or center twp road. Corner may or may not have been destroyed depending how road intersection was built.

RP to station 209+00 PI

Rear tele pole NW 85.4.
" " " NE 84.4
" power " SW 80.35'
" " " SE 78.10

73.65 WSW MHD dec NES pole
46.53 SE Rear SWS pole
52.15 N to ℄ Minn 30.

1969 71.15 ENE To Mark on Send Center Calc
72.8 WNW "

5-21-71 found ½" rod 5 & 25 ft S of ℄
Set 8-14-69 JKer B101P39.
took RPs below.
Meas south 1969. 1325' to fence west
2646.3 south to good fence west
5-21-71 used rail in center road as line fence west at ¼ 22-23 as 00

for meas south
6804
6814
- fence east 1322.5
- ℄ + roads at SW 23
2634.0

Total Mile mon to rail in + roads
5280.3 R. 52 82.3

Card # 2. 14-15-22-23 Rock Dell 105-15 #55140 (2)
10-17-73 found ½" rod set by J Kerr (set 8-14-69 by J. Kerr) dug well west into ditch section for recorded stone found nothing plenty of road yet, dep.
10-18 dug further east assuming that notes claiming corner in center of road would hold president of existing measurements. - found exact size boulder down 5' as found by Hunter 1878. P 331. A.
set 1¼ x 20" drill over stone below C/M.
Meas S. 2640.65 to C/M R 2640.66
Meas E 2631.76 to J Kerr C/M R 2634.06

RPS. 14-15-22-23 RDell

663 WSW to MHD disc on S side power pole 6804

90.6 SW to NE corner house foundation

51.02 SE to disc on SW side PR# 6814

Set by Michael Karrick 5-1854

80.00 Set post for corner to sections 14, 15, 22 & 23. Erected mound with trench, pits, charred stake and Osage Orange seeds at each angle.

9/22/88 FOUND CIM IN GOOD CONDITION

6-24-93 Found CIM in good shape 10" down in shoulder of Twp Rd running south of T.H. 30

℄ Twp Rd East 11½'

℄ T.H. 30 North 56½'