/ 10/21/92 Set 1" sq pipe cap M ¼ L

#552106

¼ corner. 20 - 21 Rock Dell 105-15.

7-1893 21 Fraser P523 No 488 & 28 on setting NW cor 28 - measured from SW 28 to this corner - fence east claimed set from corner. short 21 links - then measured on to ~~¼ 16-17~~ on fence line east recently surveyed did not took for corner. (see ¼ 16-17) which short 35 links (each ½ mile short 7 links) which make fence east at ¼ 20-21 correct north & south at that time

Frank Roeder.
Peter Lee
Bottol Magnuson.

Set by Michael Karrick 5-1854

40.00 Set quarter section post in mound with trench, pits, charred stake and osage Orange Seeds N.E. & S.W.

61.90 Road bears N.W.

10/21/92 County Surveyor set 1" Sq pipe/cap M & L between section corners, Corner falls 6' west of ℄ of C.R. #3 ; 1½' South of fence ℄ line East ; RP's CSO in PP # 6154 NW 102.98 ℄ of field drive west, north 31'

8-8-95 Blade operator had reported (6-2-95) finding cap when he was blading road. We found pipe bent on top & badly torn. We checked trav. tie & ties & found pipe to be in good position. We pulled pipe and set 6' tel/spar with cap down 10". All tourch ties fit.

(552106) 5-26-99
MW, MC, RF.

(A)

1/4 Cor 20-21 105-15 Rock Dell
Fd 1" Sq pipe w/Cap at Surface
of CR #3 6' West of ℄
Set Ref. Pipe NW of Corner
14' No. of ℄ Field Drive & 52½' W. of ℄ CR3

TC Ref pipe
⊼Rt PK in PP #6155 (1st pole South
on West side CR #3) to 1/4 Cor 20-21

316° 41' 44"	318° 26' 08"
0° 02' 08"	1° 46' 30"
316° 39' 36"	316° 39' 38"

To 1/4 Cor 20-21 (1" Sq. pipe w/Cap
VA 88° 09' 52"
Slope 64.75 Hor 64.72

Sec Cor 20-21-28-29 105-15 Rock Dell
Fd CIM 7" deep in CR #3 (6' W. of ℄) (552105)
Set Ref pipe 45½' East of ℄ CR3
and 42½' South of ℄ 100± st S.W.
TC Ref Pipe ⊼Rt PK in P.P #6182 (1st pole
South on East side CR3 to Sec Cor 20-21-28-29

131° 22' 44"	132° 46' 24"
0° 01' 36"	1° 25' 20"
131° 21' 08"	131° 21' 04"

To Sec Cor 20-21-28-29 (CIM)
VA 86° 55' 56"
Slope 69.655 Hor 69.555

NO. 447 NATIONAL PRINTWAY