1 7-22-71 found stone, set temp riser. #55230 (1)
10-18-73 set C/M over iron in complete grad.

1/4 corner 23-26 Rock Mill 105-15.

4-1878 Hunter P 334 no 328 S 23 Hans Amundson.
E C Schon.

found mound with stake remains in center, east & west pits plain. set granite boulder 6x12x17 with old stake by its side.

- 1/16 west set marked stake M & L 19.93 1315.38
- 1/16 north " " " " 20.03½ 1322.31
- 1/16 east " " " " 19.98 1318.68

plat of S 23 in armstrong book shows stone size 6x12x17.

5-21-71 co surv. meas from referenced 40 D in center cross roads at 22-23-26-27 east - found large RR tie post at south end of beedy fence row no posts only ridge property line at 1322.3 R 1315.38 mer.

Cont meas only east to center very brushy property line (no fence) at 2633.5 R. 2630.76 set nail.
R.P. Top of 4" wood cedar post in S road fence. SW 46.9
small yard rail on W side plum bag tree SSEly 55.0
- cont meas east, found eyeball line fence at 3945.7' R. 3949.44
found referenced 40D as assumed 23-24-25-26 5270.55 R5268.12.
Corner stone at 1/4 23-26 could be a little west. slight hill
east some 200' and very wet draw some 200' west (doubtful.

7-22-71. Van aerial from stone found at SE 23 over rail
in center road at 1/4 23-26 which came .5' south of nail at SW 23.
stone found 7.27 south or 6.77 south of direct line as run.
- dug and found recorded stone down 24" 7.13 S of rail .35' E.
or 9.75 S of true direct line. 7.13 - (1/2 6.77) = 3.75
or 5.68 links S direct line.

Card #2. 1/4 23-26 Rock Dell. 105-15
#552304 (2)
7-22-71 cont- set 5/8"x18" iron over stone with cypress
piece of stock tank (farm) on N side stone and glass.
road to be graded corner 1' south present road center.
- RP set 1 1/4" x 3 1/2' chin pipe south on transit line
to several old posts of line of fence near 1/2 mile south.
driven near flush with 5' heavy U staged highway
sign type post up 3' on west side pipe (no other RPS.
pipe south 60.0' 59.86 10-18-73
heavy channel iron doubled over like pictsd witness pipe
bent near double by cat- no excuse for molesting this RP
which was plainly flagged re drove pipe after trying to
straighten it out 59.86

set by Michael Karrick 5-1854

40.00 set quarter section post in mound with trench, pits, charred stake and Osage seeds NE & SW.