/ 8-5-71 found both stones left as found from N Frazer (1)

#552705

section corner 27-28-33-34. Rock Dell 105-15

6-1875 Hunter P283 no 280 S33 A Peters J. Patton.

P.L. Meas West 17.40 1148.4 then 2240 1478.4 2636.8.

Corner gone, dug extensively in road & found nothing.

settlers aver that fences running east & west were on exact line and that corner of east road fence was 28' from orig corner so established corner set stone 2/6 x 8 x 23.

- Meas south 19.98 M&L 2637.36 1318.68.

7-1893 W Frazer. P521 no 487 S33 Charley A Roeder.

found boulder stone 22 x 18 x 16 dug 2 rods square.

stone in center road and a little north of fence running east. did not jibe with Hunters measure but only stone of any description in area. left as is as corner. No Meas. of stone size.

2-1893 W Fraser P523 no 488 L 28 Frank Roeder.
Peter Lee
Bobbe Magnuson.

found corner P521 no 487.

- meas north. 39.99 to iron stake driven M & L.

8-5-71 Co surv. found nail set 7.27 in center road in line fence E & W (poor fence mest). meas 2648.62 S to nail R 2637.36
meas N to fence E & W 2643.15 R 2639.34 M & L 2642.85
Cont meas & line N to 5291.1 or 2647.95 Center road R 2639.34
dug with tractor 4'+ wide from 3' N of fence E & W south to Hunters stone found at least dug 15'- found boulder 18 x 16 x 14 ± lying in clay flat or not vertical no stakes etc .5 W 15.00 ± to nail
found Hunters stone very slightly larger (See ②) than recorded. very vertical- left Hunters stone as is after conferring with land owner Mrs Allen Skow. set ½" x 3' rod in place of W Fraser stone if one found is really it

Card 2.

#552705 (2)

Card # 2 27-28-33-34 Rock Dell 105-15

8-5-71 R.P. Hunters stone undisturbed –

bottle cap on N side new cor fence post of new fence E NE 53.75

" " " " " power pole. # 6282 N.W. 32.7

R.P. ½" rod set in place of W Fraser corner.

above cap cor fence post E 50.15

" power pole W 33.1

Hunter corner 11.5 south and 2 to 3' W of Fraser corner.

Meas south to stone found at ¼ 33-34 Hunter 2634.9 2637.36

12-71 No decision as to final corner W Fraser 2646.4

Meas north to point when set M&L 2642.85 R W Fraser 2639.34'

10-12-1973 found iron (W Fraser) and Hunters stone.
dug north and west & probed area not deep. found no
other stone above sub-soil - puncture stone found by
Bill Fraser now as a sub-soil glacial stone
- Meas on 25' ⑤ north a ± elect meas west to P.O.T
west visible from Co road #3. where point set 25 N of
28-29-32-33 total mls 5264.9 ±
Meas to N-S 1/4 line fence. 2638.24 ±
accurate meas to 1/16 stone found 12-1971-1319.45
Making east 1/2 of mls 2626.67 ± R 2626.8
- line would not be difficult to run from P.O.T on hillock
between corners on 25' offset north where 1/4 28-33 could
also be seen and 1/16 west of 1/4 28-33 with likely long pole.

#552105 (3)

Rock Dell 105-15

Section Corner 27-28-33-34 5-1854
set by Michael Karrick
80.00 Set post for corner to sections 27, 28, 33 & 34
Burr Oak 7 N 75 W 584
Dug Trench

9/25/90 FD ½" x 36" RE ROD SET AT W.F. STONE LOCATION (1971) LEANING EASTERLY ± 0.3 SET 60d SPIKE FROM P.P. TIE WEST SINCE C.P. EAST IS LEANING EAST. SET 60d SPIKE AT T. HUNTER STONE LOCATION USING P.P. TIE EXACT AND ADDING LEAN OF C.P. N.E. TO SET AS CLOSE AS POSSIBLE

12/23/93 Accepted Hunter stone location as corner. Best perpetuation of original. Gave to McGhie's For survey in NW 1/4 Sec 34

11.59 CO
2.39 W