5-9-1963 C/M set by Co Hwy Dept. over stone mon
10-10-73 found true corner reset C/M .45' due South ①

¼ Corner 32-33 Rock Dell 105-15
#553306

6-1875 Hunter P 282 no 279 L 32. C Roeder, A Peters
Corner gone no trace or evidence but Mr C Roeder avers
this his corner post south was exactly on line but had
no knowledge of measure so mens line and set
stake well down. Midway and in line fence as stated
by Mr Roeder this brought it very near where he remembered.

6-1875 Hunter P 283 no 280 L 33. A Peters, C Patten.
found stake P 282. - 1/16 south 20.03 stake M & L N10°E
1/16 north stake M & L 20.03. N1°W.
1/16 east set stake M & L 19.83 L 89¼ W.

7-1893 W Fraser P 521 no 487 L 33 Charley Roeder.
found stake P 282. set stone 2x8x18 mets place.

6-1902 H Fraser P 21 B L 33 DO Patten.
found stone set P 521 1308.78.
1/16 east found hunters stake M & L 19.83 drove iron stake
in place also set iron in place stakes at Centr 33 & 3.0 west.

6-1923 J Kerr P 392 B L 32 Hennessey.
found stone above. check as midway 2644'
replaced with 8 x 13 x 14 boulder over 1"¼ 12" iron pin

5-9-1963 Co Hwy Dept B 262. 1935. B79 P5 stone mon
found stone - set C I M. meas north 264 1.3 to iron
Disc power Pole NE 57.21 Disc tele P SE 53.6
" tele Pole. SW 72.95
" " " SE 68.36
punch mark on top of tele cable marker SE 65.4 - Same S.W. 72.08

Card # 2 1/4 32 33 Rock Dell 105-15 #553306 (2)

8-71 found 1/4 33-34 and center 33 also 1/16 corners east and west of center 33, as some were tilted or out of line with each other assumed 1/4 32-33 must be up to one foot plus south

---

10-10-93 dug with jack hammer and shovels, found county C/M down 12" carefully referenced and removed and found boulder with cross described by J Kerr. 6-1923 P 392 B and position indicator of iron below stone as described in notes
stone with cross came .45' due south of C/M
next C/M flush with road surface

over

Electronic Meas north to C/M over stone at
28-29-32-33 2641.3 R 6-1875 4006 2643.96
JKerr 6-1923 P392B 2644 or N Railway no line noted.

57.56 NE to Conc nail in old County RP dec
in PP # 6213 Co RP 57.21

6504 SE to punch mark in top center round
dome of tel cable post # 234

for correction and final placing of existing center 33 and
1/16 corners E and W of center 33 should find existing
corner posts and re run and re mark center Mile.

9.1935 C H D Book 79 page 77 found boulder with
+ Cut in top

#553306 (3)

1/4 Corner 32-33 Rock Dell 105-15

Set by Michael Karrick 5-1854

2.80 Creek 15 lks wide runs NE.

40.00 Set quarter section post in mound with trench, pits charred stake and osage orange seeds NE & SW.

(553306)F

1/4 Cor 32-33 105-15 Rock Dell

fd CIM in good Condition 3' east ℄ CR3

Set Ref pipe NW of Cor. 44 1/2'

West of ℄ CR3 & 42 1/2 North of ℄ CR108

TC Ref pipe

ART PK in PP# 6213 (Pole East of Ref Pipe)

to 1/4 Cor 32-33	
37° 11' 52"	38° 27' 26"
0° 01' 20"	1° 16' 48"
37° 10' 32"	37° 10' 38"

To 1/4 Cor 32-33

VA 87° 07' 30"

Slope 62.205 Hor 62.125

(553306)
1/4 Cor 32-33 105-15 Rock Dell
fd CIM in good Condition 3' east ℄ CR3
Set Ref pipe NW of Cor. 44 1/2'
West of ℄ CR3 & 42 1/2 North of ℄ CR108
TC Ref pipe
ART P.K in PP# 6213 (Pole East of Ref Pipe)
to 1/4 Cor 32-33
37° 11' 52" 38° 27' 26"
0° 01' 20" 1° 16' 48"
37° 10' 32" 37° 10' 38"
To 1/4 Cor 32-33
VA 87° 07' 30"
Slope 62.205 Hor 62.125