X 10-10-74 Found Stone - set 3' steel post
3/1983 set 1/2" pipe over stone ON S.W. side stone
#600706 (1)

1/4 corner. East 1/4 12 Dover 106-11 E/L Winona Co.

7-1890 Thos Fraser P444 No 429 L 12 E/L Co Line C Carter & others

corner missing, Carter avers fence running west was on line from orig corner. a boulder 5 rods west under fence was originally on line so projected fence line over boulder and intersected township line between section corners of Sec 12 and set 10 x 14 x 36 boulder as corner.

Gov't Notes: 1853

N. 40.00 Chains - set Quarter Sec. Post in mound with Trench & Pits. & deposited charred Stake & Hawthorn Seeds.

10-10-1974
found corner on S side cor. post. about 6" deep Set a steel post on the S.W. side of the stone. left the corner AS IS And did not set a C.F.M.

June, 1857 John Fraser Pg. 45 No. 67 breakdown of Sec. 1 & 12 (See survey).

Mar. 1983 Co. Surv. (RWB Survey in Sec. 7-106-10)
Found Greenish Colored pointed boulder stone - down 6" on West side of Newer Corner post fences W. + N.
No fences South or East at this time.
Set 1/2" x 9" iron pipe over point of stone.
It is ± 1.0' W. of center of Cor. fe post
No other ties taken.
Set iron pipe at 1/16 Cor. North (1321.67-1321.67)

#600706 (2)

E 1/4 Cor 12, Dover Twp. 106-11

Should get CIM in here and measure E line of Sec. 12 and compare to Thomas Fraser.

3-1980, Roger Brand: Fence corner @ 1/16 South ±1' South and 4' West of comp 1/16th. (1305.51-1305.51)
Set 3/4" iron pipe with elbow on top at 1/16 North
Tall 7' North of fence East and 1.0' West of N-S fence

[illegible] measurements to 1/4 line [illegible] East of A [illegible] between NW 1/4 and SW 1/4 on said chs. subdiv.

See Sec 7, 106-10 Traverse in Blue Book I Sec 14)