7-24-1980 Set 5/8" rod over 5/8" rod fd as set (1)
by Co. H.D. in 1943 (5½ So. & E)

X section corner east 25-36 Dover 106-11.

Winona county #603005

11-1961 Minn Hwy Dept, Du Val also Co Hwy Dept.

spike over boulder ??		in ℄ E-W Road		
MHD disc	tile pole	NW	44.45	
" "	cor FP	S	32.09	
" "	power pole	SE	89.84	

RWS see below

Co H.D. B180 76 1943 archive 1.

Dug extensively all across road in line fence N-S. found old post remains at ~~west~~ EAST ¼ 36. set corner east 25-36 a ½" rod midway NE25 and SE36 (over

Meas each mile 5267.1 on line N-S fence only.
- Meas south to corner post remains E 1/4 36 2634.8
- Meas north to corner post remains E 1/4 25 2635.7
RPs E 25-36 F cor S 23.6 - F cor N 33.3.
Dist in 10" apple SW 67.87' - Dist PP#1 up 4' ESE 86.82
later RPs dist in TP NW 32.65'
dist in FP SW 37.35' PI about 50' from corner?
Measured 2643.25' - then 2638.95'

Gov't notes: 1853
N. 80.00 chains Set Post Corner

B.T.'s	Burr oak	(No Size Given)	S 79° W	18 links
	Burr oak		N 42° W	54 "
	Burr oak		S 30° E	50 "
	Burr Oak		N 15° E	119 "

Section Corner East 25-36 Dover 106-11 #603005 (2)

7-23-80 (1980 Lemon. Book) Dug in Co. Rd 29 and found 2 hubs (1) 2x2 hub + tack
(2) 1x2 hub

The 2x2 hub fell in ℄ of road. Dug again and found A. Armstrong 5/8" rod 15" deep and 5.5 South ℄ of E-W road. This point is 5.46 South and 0.46 West of the 2x2 hub found. Drove a 5/8" x 24" rod at the surface and took references.

RP's C.S. Disc in power pole (E side) SE 50.83
Punch mark in West end 15" field drive culvert North 24.31

#603005 (3)

Sec Corner - East 25-36 Dover Twp 106-11

6-1984 Tom Ferguson Survey in Sec 30-106-10

Fd (d.p.?) in road ± 5.5' South of ℄

apparently did not dig up Co Surveyor 1980 iron