Section Corner Sec. Cor. 1-2-11-12 Dover 106-11

10-15-1974 Set C.I.M. over ¾" by 24" rod

Gov't notes: At 1853 #610105

Set post at Corner, deposited handful charcoal, made mound, trench & Pits.

10-15-1974 Dug with tractor & found spot in clay 5"x8" with square corners, it went down about 8" we also found peices of charcoal near the spot. Set C.I.M. over the spot and a ¾"x 24" rod.

R.P.'s C.S. disc. So. side P.P. # 1377 North - 31.05
Punch hole top center cor. post South - 28.89

June, 1857 John Fraser Pg. 45 No. 67 Break down of Sec 1 & 12 (See survey.)