4-18-79 Set iron at old post n stake mark #610609

1/4 Corner Center 6 Dover 106-11
Fieldbook # 14 Pg. 87
588-1887 Hunter P 419 No 408, Db, J Ketchum, H Miller.
set marked stake at true intersection.
- 1/10 north - set stake on line N 1/4 cor at Prop dist - 5 lks short of govt recording - 19.97 1/2 north then 19.87 1/2
- 1/10 south - set stake 20.01 M & b.

4-17-79 Shot spike between 2 corner posts at Center 6, a spike 173 1/2' East of the fe. corner at the 1/16th So of Center. and a spike 38.2 East (in E-W fe) of a bent iron 3/4" iron found near the 1/16th North of the Center 6 (This iron was at the corner of fence W-S-E) see back of F card apparently badly bent

4-18-1979 The County Surveyor dug at the Center 6 Dover at the calc. intersection of 1/4 lines. Found a 8" diameter dark spot with wood remains. Set a

3/8" x 18" ± iron rod with 3/4" x 8" rod along South side. Set 2 stones, one North and one South. The mark is 4.5 - 3 North and .1 East of the traverse nail set between the corner posts.

RP's: Spike in 10" Burr Oak NW 30.85
Center 16" Burr Oak in fence North 23.5
Spike in power pole SW 8.05

straightened the iron (7/8" x 30" ±) found bent over at the 1/16th North of the Center 6. It would have stood 36.7 West and 1.1 South of the traverse nail. Dug down and found it along the East edge of an old post hole. If the corner were set it would have to go appx 2.16 East and 2.50 South.

RP's to Iron. Center 18" Oak West 17.7, Center Cor. Post East 14.0
Center 28" Burr Oak NNW 27'