1/4 Corner T-18 DOVER 106-11 (1)

#610704

12-1840 Thomas Frazer (County Surveyor (Bk 4, pg 450 No 454) could find nothing at this corner

6-1900 Robert Frazer (pg 636, No 616) witnessed from, a pine cor. T-18 to see cor. 8, 7, 17, 18 to set pine cor. T, 8, 17, 18 (E-W) at proportionate dist. from west cor. He does run N. 16 links, making the north line of sec 18 79.64 chains.

1/4 Corner 7-18 Dover 106-11 #610704 (2) (5)

Support for the history

8-1853 Dont Note - William A Jones, Deputy Surveyor
East on true line between section 7 and 18
39.58 Set post at quarter section corner. Deposited handful charcoal. Made mound, fence & pits & planted Cherry seed NE & SW
19.58 To Section Corner

7-16-1980 Set a CIC/p[2] on the corner on line with the fence South and at double the measure from the comp. Center 18 on the E-W fence at the 1/10 North. Corner appx 6.3 South of line between the section corners. We also doubled the measure from the comp. Center 7 on the fence East at the 1/10 South, but this would place the corner appx 10' further South than now

set. There is a yard fence North on the North side of the road which the people living just NE of the corner say replaced the old fence running North. (The old plat book shows the road bent north from the corner to the 1/16 North and then bent East so we decided the fence at the 1/16 could be less reliable than the fence at the 1/16 South)
The corner is set under the fence South and 33' South of the center of the road.
RP's: Center of cut off power pole East 51.9
CSD on E side end fence post of fence So North 8.01
SW corner of concrete floor of patio deck
on South side of home NE 115.35
S-1135, 1/4 Co. T-13: Set survey marker sign and post 3 South of