¼ Corner ¼ Cor. 12-13 Dover 106-11
10/8/91 Set Cim over ½" iron #611204
Gov't notes: Oct. 1853

Midway @ 40.10 chains
Set Post at Qr. Sec. Corner, deposited Stone 6x5x1
Made mound, Trench & Pits.

11/9/91 County Surveyor fd 60d spike in ℄ line of fence east set by R. Brand, this spike is 0.4 west of our former trav pt. Dug and found 3" diam. black mark at clay line followed it down 10" getting smaller to point in last 3". The old road was on dark soil 2' deep. the clay started at ± 2½' deep. The black mark is ± 5' east of ℄ N-S twp rd. Dug to 10' east, 4' north & 4' So. & 1 west of trav nail dug up to 13½' east ↓

7/9/91 Cont.
Found nothing further, set 120d spike @ stake mark location.
10/8/91 Set CIM over 1/2" iron at stake mark location fd 7/9/91. the corner is 5' east of ℄ N-S twprd and 1' south of fence east. Rpts
CSD IN PP# 47826 SSW 57.59
℄ OF FIELD DRIVE EAST SOUTH 29'