1 · 5/19/92 Set CIC/P²

#611405 (1)

section corner 14-15-22-23 Doner 106-11

5-1881 Hunter P 369 No 360 L23 Cuppen J Fraser

No mention of corner only that the Book 5 Page 122 Zacher.
Same survey found
N¼ cor 23 lay with 1 foot of midway. Corner post stub
-39.86 from N¼ 23 West said by John Coffin to
-39.87½ " " " East be where corner stood.

– no mens on RR notes.

C.L. Cuppen

9-1902 W^m Fraser P416 Set line E¼15 to E¼22 W^m Thompson

~~found~~ stone between 2 posts as corners

GOV NOTES - 1853 - ~~J BALL~~ William A. Jones
SET SECTION CORNER POST 80 chs NORTH OF 22-23-26-27
LINE BURR OAK (8 INCH) S 4 1/2 E. 650 LKS.
deposited stone 8"x6"x2"

June, 1857 John Fraser Pg. 44 No. 66 Shows Sec. Cor.
(See Survey for Interior breakdown of Sec. 23).

10/21/91 County Surveyor probed at old fence corner
int a transmission pole now used as cor. post
to fence east & south hit stone top down 6"
from surface the stone was 4"x8"x14" but to
me it was upside down from the way a surveyor
would have set it, but the end that was up
had a small indentation that seemed to be a
drilled spot in the middle. Found stone below
other stone, 4"x6"x10" standing vertically. There
was a post mark north of stone but somewhat
disturbed by the digging of the trans pole. →

SECTION CORNER 14, 15, 22, 23 DOVER 106-11
10/21/91 Cont. Clay was 2½' deep, fd chalk
soft spot running 8" down into clay.
Set rod at large stone locat...
5/14/92 County Surveyor Set CIC/P² @ large
stone locat on fd 10/21/91. The corner falls
1' South of trans pole
RP's CSD in W side trans pole North 1.56'
The corner lines with fence E-S
nailed sign to trans pole NE

#611405 (2)

9-15-93 MnDOT FOUND CIC/P² AND TOOK RPS.
CND W SIDE PP NE 1.93'
CND TOP OF 1ST FENCE POST S OF PP 13.36'