8-29-1963 set C/M over boulder. (1)

#611504

1/4 corner 15-22 Dover 106-11.

9-1889 Thos Fraser P435 No 422 L22 Ricker.
found long stone between old & new corner posts. 30"x3"
very large boulder north of corner.

5-1895 JT Fraser P568 no 520 L22 Hart, Taylor.
found corner P435 no mark.

8-1963 J Kerr. found pointed boulder.
set C/M above boulder

(over)


Disc power pole NW 1.87

power pole is 1.0 north of corner and west.


RW notes 19.53 the south to 4 racks.

GOV. NOTES - 1853 - J. BALL

SET 1/4 SECTION CORNER POST MTL 39 91 2634.06

10-15-1979 Dug out Kerr's CIM (top broken off). The CIM was over a 

boulder. The corner is on the West side of a huge boulder. Since Thomas Fraser described this corner as a 30" x 3" stone on the south side of a large boulder and since our line from 5 1/4 Cor ## 22 (Corner set at Fraser's mark) over the CIM at the center 22 would come 3' East. We dug East from the CIM and along the South side of the boulder as follows: We did not find anything. We set Kerr's boulder back (at its location) inserted a 1/2" rod on its E side. Set a new CIM over the stone. The corner is 2 1/2' SE 1/4 of the center of a huge power pole used as a C.P. to fence N & E.



1/4 CORNER 15-22 DOVER 106-11 #6N504 (2)

9-6-95 MNDOT FOUND C&M AND TOOK RPS

CN + D	E	SIDE	WOOD	FENCE POST	SSW	19.88'
CN + D	N	SIDE	WOOD	FENCE POST	SW	1.00'
CN + D	S	SIDE	PP		NW	2.00'