X 9-24-1975 Set C.I.M. over 5/8"x12" iron rod by M&L
#611706

1/4 corner 17-18 Doner 106-11.
1939 Co Hw Dept B 101 p6.
assumed corner no ties

Disc. Ab pole	NE	42.88
" "	SE	69.20
North to 7-8-17-18		2615.3.
South to 1/4 19-20		5292.0

T. Fraser 1890 p. 450 No. 434
Says he could find No Corner

R. Fraser 6-1900 p. 686 N. 610
indicated No Corner found went right by it. Apparently

9-24-75 Dug at corner location but found road had been cut to clay 1½' deep. Set C.J.M. over 5/8" x 12" rod M&L as ~~indicated~~ indicated by Robert Fraser. Corner in "T" intersection, 8' E of ℄ (local) N-S road and 12' S ℄ road E. Dug 5' x 8'

R.P's: CSD N. side pp # 81 NE 99.72
Spike & CSD S. side 36" Elm SW 73.94
Telephone box up 2' (top center) NW 55.4
SE corner of pole shed (metal joist above boards at ground level) NW 172.0 (slope)

GOV. NOTES 1853 - J BALL — SET ¼ SECTION CORNER post M+L 40 chs 2640