X 7-10-1975 Set 6 I.M. over a 3/4" x 9' rod #612005 #1
3-20-95 CHD SET 1" SQ PIPE W/CAP.

section corner 19-20-29-30 Dover 106-11.
9-1892 2hos Fraser P 497 No 469. L 16-20 4 parties.
. Corner gone - re located by meas L E 20 to L W 19.
or ~~39.94 1/4~~ ~~4 times~~ 23 lks short in 2 miles
W 1/2 19 - short 39.94 1/4 - 39.94 1/4 East
39.94 1/4 - West Then 39.64 4 to SW 19
Meas W 1/4 20 south to W 1/4 29 but found meas way short so meas from W 1/4 20 to L W 29 where corner was stone in center road. This placed L W cor 20 in middle road. Meas over ran 46 links
Planted stone at this point in center intersection
- 1/16 north set limestone M & L 20 0 7 2/3 (1325.2
- set boulder 57 rods west of L 1/4 20 as established in ones

this survey on line Then 25.69 1/4 chs West to
establish section corner making total 1/2 mile 39.94 1/4.

60 D nail set 1939 B101 P4 +/-
Co Hwy Dept dug for corner 9/30/1972 Note page 68 found nothing
assumed corner, set corner on line ~~from wood~~. Stone Sq.
R.P. Sta 131+29.0 a P.I. Δ 0°3' Rt.
Sp in 15" spruce NE 74.7', Sp in 10" spruce SE 71.4'
Sta 1/4 1920 15799.4 or 2650.4

7-1975 dug with tractor but found nothing
Road had been ~~cut~~ cut down to bedrock.

7-10-1975
Reset the corner with a 5/8 I.M. over a 3/4" x 9"
rod. Corner lies 7' East of the ℄ Co. Rd #32
2' South ℄ of road West and 8' South

#612005 # 2

Section Corner 19-20-29-30 Dover 106-11

of ℄ of road EAST.

Reset this corner by doubling the line ; meas. from the EAST AS per T. FRASER Survey of 1892

R.P.'s

C.S. disc in	Power Pole	N.E. 43.46
C.S. disc in	Power Pole	N.W. 57.40
center	tele pole	S.W. 44.1

GOV. NOTES - 1853 - J BALL

SET SECTION CORNER post. 80 chs NORTH of ℄ 29-30-31-32

ELEV. 1276 LAND SLOPING NORTH IN VALLEY TYPE AREA

(over)

Co. H.D. 1939 Bk 101 p. 76 Sec. Cor. 19-20-29-30
Produced line from S.W. Cor (apparently S.W. Cor. 29- RWD)
thru 1/4 cor. to here and dug extensively all about
the intersection. Found nothing so set a point
on the produced line at the center of road
running west

6-5-95 COULD NOT FIND CIM SET IN 1975 IN CR #32. WE RAN IN THE SECTION LINE FROM THE WEST + SET A P.K NAIL PRORATED AND ON LINE FROM WEST TO BE @ 1975 LOCATION. TESTED MEASURE + ANGLE NORTH TO CHECK POSITION. WE WILL SET FINAL MONUMENT AFTER BITUMINOUS OVERLAY THIS SUMMER.

9-20-95 - CHD SET 1" SQ PIPE / CAP.

SECTION CORNER 19-20-29-30 DOUCK 106-11 #612005 (3)

6 16 95 - FOUND P.K. SET BY CO. SURVEY CREW @ 1975 LOCATION.
SET 1" SA PIPE W/CAP IN NE COR CROSS ROADS INTERSECTION.
℄ CR # 32 WEST 46' ℄ TWP RD SOUTH 37'.

T@ REF PIPE
ART OLD BLUE EYOTA WATER TANK TO SEC COR 19-20-29 30
280° 08' 57" dh 00 281° 35' 49" dh 01
0° 24' 41" dh 01 1° 51' 35" dh 00
279° 44' 16" 279° 44' 14"
TO SEC COR 19-20-29 30 (P.K.)
VA 90° 04' 11" dv 08
SLOPE 60.695 HOR 60.695