7-1-1975 Set C.I.M. over 1¼" Pipe Found #612105
section corner 20-21-28-29 Dover 106-11
5-1891 2hos Fraser P449 No 432 L 21 Bracket, Shubs.
corner was gone but Mr. Leat claims his corner
post had been set 2 rods east of our corner when
standing. He had a stone planted where that post stood
used this to set point for survey.
- meas east 40.01 1/2 to temp point set midway
only to set center 21

9-1892 21m Fraser P497 No 469 L 16-20 for
H Crullenden, J Dickey, H & J Drysdale.
GOV. NOTES - 1853 J BALL
SET SECTION CORNER POST 80 chs NORTH OF 28-21-32-33
ONLY

found tree planted where corner post stood year before., used tree to determine corner.

- meas west 39.94 1/4 to 1/4 corner 2636.37

7-1-75 Dug with backhoe in "T" intersection, found 1¼" pipe 18" long 2½' deep. Pipe in E's road N and N-S road. Set C.I.M over pipe. Corner falls 33' west of tree used by W. Fraser to set corner.

R.P.'s 60d spike in 42" elm E 33.42

Punch hole in culvert (4") SSW 39.52

Punch hole in culvert (1") NNW 45.21

See Cert of Location by E.C. Burns 1927 - calls for pipe in blue book

Rec'd this Cert from Mrs Harman 8-15-1984