#612209 (1)

8-30-1963 set C/M over 1/2" rod in stone found.

1/4 corner Center 22 Dover 106-11

9-1889 Thos Fraser P435 no 422 S22 Ricker
set iron rod 2 1/2' long and stake miles lines

5-1895 2t Fraser P568 no 520 S22 Hart Naylor
field plowed. run E-W 1/4 line & meas as on P435
found. remains old stone by no iron
set stake and planted stone.

-1/16 east set stake M & L 20 04 1/4.

over)

8-1963 found stones & stake remains after elaborate procedure.
set CIM over ½" rod below plow:

Rec in corner post of field pasture fence NW 277.0

Corner lies east of field pasture fence running north and south. 91.25' corner to fence line at a point 262.7 south of corner post above RP.

10-15-1979 dug out Kerr's CIM to verify this corner. We found only piece of limestone packed around — no stake or stone and no ½" iron beneath monument, only a 3" or 4" piece of pipe. dug West 1.5' ± and East 2' but found nothing. Set the CIM back at Kerr's location

#612209 (2)

1/4 Corner Center 22 Dover 106-11

11/30/89 Roger Brand found cirn 12" deep in cultivated field, corner is ± 300' west of fence east which runs NE-SW and is ± 300' south of fence along northedge of field It lines up approx with fence corner & PP at N 1/4 22 & with tree line near S 1/4 22 ; with fence running from N 1/4 22 to about 100' east, but line is over the ridge ± 300' W of center 22

11.190 Roger Brand took Rp's with EDM (FENCE W/ SE)

317.16' N 33° 11' 34" E TO PK IN TOP WOOD COR. POST (FENCE SW; NW)

410.23' N 72° 19' 52" E TO PK IN TOP WOOD COR. POST

DISTANCE BETWEEN PE's 258.94' S 57° 02' 00" E

9-6-95 MnDot found CIM Took RPS

C.N. + D IN TOP WOOD [redacted] FENCE POST NW 277.21'

PK NAIL IN TOP WOOD FENCE POST NE 317.13'

PK NAIL IN TOP WOOD FENCE POST NE 410.03'