#612405 (1)

/

Section corner 23-24-25-26 Rover 106-11.
6-1881 John Fraser P370 No 361 S25 Rodeno-Taylor.
found govt section corner.
-1/16 south, set limestone 3x4x20 M&L 19.98½ (1319.0

12-1894 H Fraser P561 No 515 S24 H H Ruler
found remains old stake by old fence post.
Stated NW & NE Brass & stamps marks still plain
planted stone in place of old stake, drove new stake also.
-1/16 east, planted stone M&L 19.99 (1318.0

over

Gov't notes: Oct. 1853

Set post at Corner

B.T.'s Br. Oak 12" S 45° W 168 links

Br. Oak 10" N 71° E 149 "

Br. Oak 8" S 46° W 117 "

Br Oak 9" N 64° W 297 "

June, 1857 John Fellows Pg 43 No 65 shows Sec. Cor.

See Survey for Interior breakdown of Sec 26

June, 1857 John Fraser Pg 44 No. 66 shows Sec. Co.

Meas. west 40.25 chs Meas. North 40.00 chs,

8/14/84 SEC COR 23-24-25-26 DOVER

FENCES E-N-N, NO BRG. TREES TO FIT FENCE CORNER. FD 3" THICK x 15" W. OE x 24" LONG LIMESTONE LEANING SLIGHTLY NORTH BUT DUG IN ! STANDING TOP DOWN 6" ON THE NORTH SIDE OF THE STONE WERE MANY PIECES OF LIMESTONE PACKED AROUND OLD ROTTED POST STUB WHICH WAS .75' N & .25 W OF THE STONE, DROVE A BOARD AT STONE LOCATION AND STOOD STONE BY TREE 20' ± WEST

CONT. #2

SECTION CORNER 23-24-25-26 DOVER 106-11 (2)

8/14/87 Cont. STONE LOCATION 2' So. & 2' E OF LINE OF FENCE N-E-W

#612405

1/16 EAST OF SEC COR 23-24-25-26 FD FENCE CORNER TO FENCE E-W-N, BUT NO [redacted] W.F. STONES