/

#612409

1/4 corner Center 24 Doner 10 6-11.
12-1894 Wm Fraser P561 no 515 L24 M W heiler.
No corner in place. Mr Stearns owner of SE 1/4 Sec 24
avers he set corner post of fence south. just 2 rods
south of corners when standing.
-1/16 west - set stake 19.95 N&L. 1316.7

T. Hunter
RR line 36.56 chs from N 1/4 24 south to center raile
2413

6-1857 John Fraser P30 no 47. subdivision
E-W 1/4 line 4 quarters of 19.93 each 1315.4.
N-S 1/4 line 39.90. 2633.4 N 1/2 S.

Co. H.D. 1919 - B. 28 p. 45

at about appx. Sta 538 + 10 ± — Should be near center 24

However - 2 small curves in road alignment shown in notes therefore ℄ road probably Not on or near Center Sec. - Line should be Taken across whole Section for N-S Location of Center Sec. 24 - R.B.