9-20-95 CHD SET 1" SQ PIPE/CAP

#612504 (1)

1/4 Corner 25-36 Doner 106-11.

5-1881 John Frazer P 370 No 36 1/25 N. Rubens
H. Taylor.

found govt corner "post"
no mrks - no description
- 1/10 west, plat shows corner in place
now county road with Township road south

B180 P76 1943 corner assumed Co. H.D. Sta 105+92.5 43.56 Corner
PI Δ 0°10' RT

Meas east 2643.25' west 2638.95' Total mile 5282.2

Page 5 Book 180 set 1/2 rod at a point midway between fences found at 1/4 Corners North and South, and in line with fence North for ~~1265~~ 25 ~~[illegible]~~ over
16-15-36

Gov't notes: Oct. 1853
Set Corner 40.01 midway
Set Post at Qr. Sec Corner, deposited handful of Gravel,
Made Mound, Trench & Pits

Page 5,6 and page 16-17 Book 180 Continued.

~~[illegible]~~ then run line To Sec Cor EasT and assumed this 1/4 Corner 25-36 on line and midway, buT Set 2"x2" hub in line with fence running North and as P.O.T. on Sec line as run, which is not midway Sta. 132+31.75

P. 17 Bk 180 Topog
Shows ℄ Twp Road To South at Sta 132+26
and fence To North @ Sta 132+32 = 29' LT
@ sta. 132+49 Beg run Walnut Trees 31' LT
from Topog ℄ Travelled Road appears as ± 5' So of ℄ as run
@ Sta. 145+53 - 1/16 fence runs North at 26' LT To Cor. of fence
@ Sta 158+75.0 = Sec. Cor. 25-36 on Co. line

1/4 Corner 25-36 Dover 106-11 #612504 (2)

7-23-1980 (1980 Remon BK) 1/4 Cr 25-36: Road cut to bedrock at ± 24". Dug large hole across ℄ of E-W road and in line fence North. Cl. Armstrong iron (at E. 25-36) and the 1/16 fence West agree with the location E-W. Found A. Armstong's hub 31 ft. out from the line of Walnut trees on the N. side of road. Continued digging South and found another 1" x 2" hub and the whole area had been dug extensively. This hub was 6.1 ft South of Armstrong's 1 2x2 hub. Tied out both hubs until location can be proved further from 1/4

lines in 25 & 36.
R.P.'s to Archer hub:
C.S. Disc in top of corner post over
C.H. Dept disc NW 45.43
C.S. Disc in top of corner post SW 52.67
This hub is 3' North ℄
RP's to South hub:
C.S. Disc in top corner post NW 49.84
C.S. Disc in top of corner post SW 48.60
This hub is 3.0 South of ℄

9-20-99 - CHD SET 1" SQ PIPE W/CAP

1/4 CORNER 25-36 DOVER 106-11 #612504 (3)

6-14-95 - SET PK NAIL @ ARMSTRONG HUB LOCATION 3' NORTH OF ℄ CR "29 FROM TRAVERSE POINTS USED IN 1980. THE CORNER POST TIES ARE NO LONGER ANY GOOD. SET 1" SQ PIPE W/CAP ON W SHOULDER OF N-S TWP ROAD 82' SOUTH OF THE CORNER + 12' W OF ℄ N-S TWP RD. T @ REF PIPE

ART TOP CENTER RADIO TOWER ENE TO P.K. @ 1/4 COR 25-36
287° 43' 16.5"

TO PK @ 1/4 COR
VA 90° 21' 17" dv 07
SLOPE 82.58 HOR 82.58