X 7-24-1980 Set 5/8" rod near & Road in Same place (1)
as set in 1943 by Line from East & in line fence South

section corner 25-26-35-36 Dover 10 6-11.

9-20-95 CAP SET 1" SA PIPE CAP

#612505

No records.

Co H D B180 P76 1943. dug found rocking
set 1/2" rod on line fence S. midway between 2 assumed
1/4 corner fence corners - 2634.4'

RPs dist in NE cor school SW 77.3
dist in F.P. NW 82.1
dist in corner F P S 18.75'

Meas east 5282.2 To corner set in line fence N & S
and midway N & S. of 2 miles N S
Meas west 5290.2

over

Gov't notes: Oct 1853
Set Post at Corner
B.T.'s Br. Oak 4" N 45°E 137 lnks = 90.42
white Oak 7" S 50° W 66 " = 43.56
B. oak 8" N 40° W 48 " = 31.68
Br oak 6" S 14½° E 62 " = 40.92

Co. HD Field Bk 180 P. 16 Topog indicates old school Bldg & yard To S.W. of This Sec. Cor

Co. H D Field Bk 18[illegible] P 35 [illegible] indicates E old Road and I 2' North of E as used for regaining possibly the E as run after locating the section corners For ¼ Corners N. & S

7-24-1980 (1980 Remon BK) Sec Cn 25-26-35-36: Dug but road cut to bedrock at about 18". Closed hole. Reproduced A. Armstrong line from East—5/8" rod over 2x2 hub and set a 5/8" rod for a sec. corner. This corner falls in E and in line fences N & S

June 1857 John Fellows FB 43 No 65 Shows Sec Cor-Meas North 40.01 chs West 19.19 chs.

SECTION CORNER 25-26-35-36 DOVER 106-11 #61X505 (2)

6-14-95 - 5/8" IRON GONE. SET PK NAIL @ 5/8" IRON LOCATION FROM 1980 TRAVERSE. SET 1" SQ PIPE W/CAP ON EAST EDGE FIELD DRIVE WSW OF CORNER. REF TO PIPE & FIELD DRIVE WEST 9'
& CR #29 NORTH 36'

T @ REF PIPE

RT CENTER OF LIGHT ON TOP RADIO TOWER ENE TO SEC COR

292° 50' 33" dh 06	294° 15' 34" dh 09
3° 00' 33" dh 02	4° 25' 31" dh 02
289° 50' 00"	289° 50' 03"

TO SEC COR 25-26-35-36 (P.K.)

VA 89° 13' 26" du 08

SLOPE 37.26 HOR 37.26

9-20-95 - CHO SET 1" SA PIPE/CAP