X

#612506

1/4 corners 25 - 26 Dover 106 - 11.

6-1881 John Fraser P370 no 361 L25 N Rubens H Tyler.

found govt 1/4 post

- 1/16 north - set limestone 3x4x20 M&L 19.98½ (1319.0

11-1961 Minn Hwy Dept Du Val.

found 8 x 12 x 14 boulder with + at crossfence 1.0' below ground surface, ~~also~~ Co Hwy dept Book 180 p. 77

MHD Disc Fence post west 17.4. found working assumed cor P. as corner - may not have dug at all.

" " cor " " north

" " " " east 8.5 over

- Meas south 2634.4

Gov't notes: Oct. 1853
Set Post at Qr. Sec Corner, made Trench
one BT. Br. oak 8" N 2°E 625 lnks

7-23-1980 (1980 Remon BK) 1/4 Cor 25-26: Dug on South side RR the corner post (now post in N-S fence appx 10' North of N'ly I-90 R/W fence.) The old fence West is now gone and although the old fence East is still there most of the posts are on the ground (including the one with the MHD SRP). There is no SRP in the corner post or the post itself may be a replacement. Dug down 1' and found a boulder 7x17x23 lying flat, the center of which was 1.8 South of the post. There were two other boulders just West of this. Set a nail on the South side of the corner post at the base of the post as a t.p.

Jones 1857 John Forbes Bk 43 No 65 shows 1/4 Post 6 1/2 North 20 Chs.
Meas South 40.00 Chs. to Sec Cor.