#612604

1/4 Corner 26-35 Dover 106-11

Govt Notes

Set 1/4 sec. Corner post M+L 40 chs.
made mound, pits, trench, + planted
Cherry seeds. Deposited stone
7"x6"x2"

Co. H.D. 1943 C.A. Armstrong, chief of party Field Bk 180

p. 76-77 - did not dig here as former Road Grading had cut several feet below natural Ground into rock.

Page 4 - Sta. 79+47.7 indicates 1/4 Corner intended to be placed Midway & Line between Section Corners.

Page 14 - Topog. - Culvert inplace ± 200' East which the ℄ of Travelled road ± 7.4' N. of ℄ road as run If ℄ old roadway is any good then 1/4 Cor location Could be ± 7' N. of present ℄ Co. Rd #29

"over"

However, road and fences appear in Topog. Notes as not Too Straight

Co. H. D. field BK 181 p. 25 X-sections indicate old ℄ Road about 4' N. of Line as run for Sec. line ℄. and old ℄ Road about 2' Lower than ground 20' South and about level or slightly above ground at 20' North No x-section Taken right at this 1/4 cor. Location but was taken ± 15' East @ 79+68

June, 1857 John Fellows Pg. 43 No 65 Shows 1/4 Post
(See Survey for breakdown of Sec 26)