X 10-31-1979 Set C I m 9-20-95 CHD SET 1" SA PIPE/CAP #612605 (1)

section corner 26-27-34-35 Dover 106-11

No records

C H D. B 180 P 76 1943 corner stone claimed once in place believed by residents as corner. Mr Coulson says it was in center E-W road and 12' ± west of fence north. - Mr Laramie also says it was in center E W road but 4 or 5 feet west of fence north - no further comment but dug near 20' long from fence north (west) to bed rock.

RPs. To point used ½" Dice in corner FP "S" 27.5'

Dice in tele pole N S W 94.15

1961 RPS Dice in Tele pole N N E 39.25

Dice in P pole E 33.55

(over)

Meas east 5290.2

Meas west to 2621.5 fence line &.

GOV. NOTES - 1853 - J BALL

SET SECTION CORNER POST 80 chs NORTH OF short 34-3

CORNER IN E-W COUNTY ROAD #29 BLACK top

FARM boundary north - EAST - WEST, common south.

10-2-1979 Dug into the backhoe from a point 8' East of the C.H.D iron found and used as a traverse point East for 8', North 2' and South 2' by 2' deep. The area had been cut to ~~clay~~ bedrock in road construction. We are digging to cover the ℄ and line of fence North. Found nothing.

10-31-1979 Set a CIM over a ½" x 8" rod 12.0 East of C.H.D. (A. Armstrong) iron ⊕ in line with the fence North and on a continuation of the line from Sec. Cor. 27-28-33-34 over the C.H.D iron (removed). The corner is in ℄ E-W road.

RP's: Punch hole top E. end C.M.P. in field drive South SE 34.08

⊕ CSD E side power pole SW 35.52

⊕ punch in E side 7" pipe gate post NW 41.92

Section Corner 26 & 27 34 35 Doc. 106 11 #612605 (2)
June, 1857 John Fellows Mg 43 No 45 shows Sec Cor.
(See Survey for Interior Breakdown of Sec 26

6-15-95 - FOUND CIM IN GOOD SHAPE. SET 1" SQ PIPE W/CAP ± 2' EAST OF FENCE LINE NORTH & 50' NORTH OF ℄ CR #29.

T@ REF PIPE

4RT P.K. IN P.P. (2ND ONE W OF SEC COR) WSW OF 6' TO SEC COR

286° 29' 43" dh 07
0° 04' 44" dh 01
286° 24' 59"

288° 12' 45" dh 08
1° 47' 45" dh 02
286° 24' 58"

To Sec Cor 26-27-34-35 (CIM)
VA 90° 56' 03" dh 03
Slope 49.55 Hor 49.55

9-20-95 - CHD SET 1" SR PIPE/CAP