X 10-4-1979 Set CIM #6126006

1/4 corner 26 27 Dover 166-11. ①

4-1871 Perry by Hunter, P182 No 192 & 27 N N Pike found stake as 1/4 post on line and under fence -1/16 west - set stake N 4 L 19.94 (13/6.04).

11-1961 Minn Hwy Dept DeVal HOT station 1330+04 131.87
found boulder at fence corner intersection [redacted] 12"x15" 12" above ground.

N 4 L dec fence post E 43.92
" " steel fence post S 46.2

GOV NOTES - 1853 - J BACK
SET 1/4 SECTION CORNER POST. MAL 40 LKS 26 40
deposited stone 6" x 4 x 2"

Fd in place hardhead boulder at inter fence Cor. 12" above ground (12"x15" stone)

10-4-1979 Found remaining 28" of old post (~~coffee~~ referred to by MHD) packed in stone. Dug 2' x 2' hole on the West side 3' deep to clay but found nothing. Drove 1"x 28" drill steel at the post location. Set a CIM over the drill steel and set the post on the West side of the CIM This corner in cultivated field 34' North of the North R/W fence of I-90.

RP: 4" topped CIM R/W Monument 1½' N of N. R/W Fence I-90 South 32.5

10-10-1979 We dug from the CIM West 7', North 2', and South 2' by 3½' deep to cover double the measure from the stake found at the Center 27 on the post found at the 1/16th East (Pt. came 6.4 West of the CIM.) We found nothing. This point would fit the main line of the fence South. There is 2' of fill over the black dirt here and we dug through what appeared to be an old road in the fill ½' to 1' above black dirt.

1/4 Corner 26 21 Dec. 106 11 #612606 (2)

June 1857 John Fellows Fig 45 Notes Shows quarter post

(See Survey for breakdown of Sec 26