5-10-77 Set C+M
10-31-79 Rest 1.93 N and 3.34 E
#612804 (1)

1/4 Corner 28-33 Dover 106-11

Govt Notes
set 1/4 Sec post 40 chs
made mound, pits, trench, + planted
Harry seeds

5-9-77 (1/16th E) with backhoe at T.N. Found 9" x 11" x 16" boulder with old stake on N. side 2' deep Corner in ℄ E-W road and 1' W of fence North Set 1/2" x 12" rebar in stake hole and 3/4" x 8" rebar on the E side of the Stone. Corner (stake) 2.15 N and 2.85 W of T.N. Left nail at surface.

LRPs
S 57.85'
E 8.0

(10-31-1979) 1/16th East: Set a 5/8" rod on the 1/16th corn 1.0 south of the stake found and over the stone. This corner 1' So ℄ and 1' West of fence line North.

1/4 Cor 28-33

5-9-77 Doubled line and measure of 1/16th East. Point came appx 4' West and 2 1/2' ± N of the T.N. Dug from T.N. W 10', E 8', N 8', and S 5' 2 1/2' deep to clay. Road on clay. Found nothing.

5-10-77 Set a CIM over a 1/2" x 15" rod at this ~~dot~~ location. Corner 2' N. of ℄.

R.P.'s: CSD in Telephone pole NE 127.20

CSD in telephone pole SW 105.65

10-24-1979 Dug 3 to 4 more feet off the North edge of the hole dug in 1977. Hole now reaches 8 to 9' North of the CIM there. We were digging to cover doubling line and measure from a location ~~a location~~ for Sec Cor 27-28-33 5-6' So and 3.34 West of the CHD location over the 1/16th West. Found nothing.

#612804 (2)

1/4 Corner 28-33 Dover 106-11

10-31-1979 After correcting Sec. Cor. 27-28-33-34 and using the stone instead of the stake at the 1/16th West, We reset the corner 1.93 North and 3.34 East to be at double the line and measure from Sec. Cr 27-28-33-34 over on 1/16th West. The corner is 4½' North of ℄ E-W road.

RP: Punch hole top E end CMP in field drive South.
SW 40.7