GOV. NOTES – 1853 – J BALL Card #1
SET 1/4 SECTION CORNER POST MTL 40cm 2640.
9-28-95 CHD SET 1" SQ PIPE W/CAP. #612906
1/4 corner 29-30 Dover 106-11.

~~No records.~~

11-1961 Mun Hwy Dept Da Val. Mon S. 2695.1
found. 4x6x22 limestone 8" deep & W. Brundage S 148.43
sucer in place.

MHD disc	fence corner	E	33.6.
" "	" "	W	33.65.
" "	" post	NE	45.25

1939 CHD B101 P75.
found pointed boulder. 22x12x8
RP. Lp cor FP E 32.2. Hub west 91.8 (throat tie.
Lp PP NE 50.3 Hub east 54.15 (over

corner at Sta P.O.T. Note: Did not have sec. cor. North
105+16.1 2612.9 North
Sta 19-20-29-30 131+29.0 2696.4' South.
Sta 29-30-31-32 98+19.7 -5309.3 O.K.

Note: Co. H.D. did not have sec. Cor 19-20-29-30 at this Time. RWS 5-1982

T. Fraser Field Book 8 p 30 1891 ?

found Stone at ¼ post South of E (illegible)
but it gave one quarter 78 lks more than the other we
we went to the Section corner south
Meas. from W.¼ Ac To S.w 29 (1½ miles overrun 46 lks.)
Set Section Cor 19-20-29-30

Dug

5-10-77 Dug at point in ℄ at Mont Hwy Dept. measure from ℄ of the West bound lane of I-90 which came in line with fence E&W Dug 10' deep with backhoe and dimore by hand into clean clay. Apparently area cut in the construction of the I-90 bridge. Found nothing.

RFS to Nail PK in pavement SW 2000
Nail in top of quard post NW222

#612906 Card # 2

1/4 Corner 29-30 Dover 106 11

Feb 1980 Mike W. found a survey in the 1st 100 Pages of Book A that could be Sec. 30 106 11 by Nelles & Dec. of Corners June 1863 P.C. Compton Page 11 No. 102 (Babbitt & others) shows stone (12x18x22) with glass beneath as 1/4 Cor.

5-14-82, 1/4 Cor. 29-30: Set a spike from reference points taken 5-10-77. Came in ℄ N-S road. Fence East now gone. 1939 C.H.D tie of 71.8 East to hub from spike set comes 18' into cultivated field. 1939 CHD tie of 54.15 East to hub from spike set comes at the foot of slope and at edge of field. Dug 3'x3' at this location but found nothing.

6-16-95 - FOUND SPIKE SET 1982. SET 1" SQ PIPE W/CAP NW OF CORNER ON W SHOULDER CR #32. & CR #32 EAST 20 1/2'.
NORTH END I-90 BRIDGE SOUTH ± 90'.
~~4~~ @ REF PIPE
4 RT EYOTA BLUE WATER TANK TO 1/4 COR 29-30

202° 26' 08" dh 01	203° 51' 09" dh 00
0° 11' 37" dh 05	1° 36' 42" dh 02
202° 14' 31"	202° 14' 27"

TO 1/4 COR 29-30 (SPIKE)
VA 88° 24' 06"
SLOPE 41.85 HOR 41.835

9-20-95 - CHD SET 1" SQ PIPE W/CAP.