X 4-8-78 CIM #613006 (1)

1/4 Corner West 1/4 30 Dover East 1/4 25 Cyota.

6-1913 D Williams P224 B L 25 mail Keefe

Quote "We went to point "F" where we found a boulder in the center of the road verified as being 1/4 Cor of sec. 25 by adjacent land owners. Running a random line west to a point "G" 2640' west of "F" and 7.5' south of our random line we found a boulder beside which was an old cedar stake. The stone was on line of N and S fence and 2' south of a row of willows running E and W. We continued our random line west a total distance of 5280' marking south 15' from the point. We intersected our stake at "D" on our N-S section line. We dug in and around the one,

point to a depth of 4' but could find no stone. We then set an iron pipe 1" dia by 4' long. 6" below the level of the road. We placed rock around it and witnessed it to a bearing tree as follows N 46° 21' W to Cottonwood tree 20" in diameter. Staked line between Pond 2 which fell a few feet North of present old fence & corner by a flat rock - Mean 2640 N to A and A to F Iron pipe 6' west of true line and 7.3 North so the 2640 adjusted should be 2634 actual to stone and Center stone would be 3.65' N of direct line.

Feb 1980 Mike W. Found a survey in the 1st 100 pages of Book H that could be sec 30 106 11 by Names & Desc of Corners June 1863 PC Compton Page 11 No 102 (Babbitt & others). shows stone (11x10x18) with glass beneath No South. Stone (8x10x14) with glass beneath

#613006 (2)

Card # 2 W ¼ 30 Dover East ¼ 25 Eyota
recorde in Co Hwy dept corner book by Minn Hwy Dept
about 1961
found large limestone 2' diameter with top broken off
5½' down, found old hard 1½' down over stone
2 RPS in headwalls likely Dorozee
73.10 NW to W inwd 1 foot down
74.30 NE to E " brace
35.9 SE down on fence post

Gov't notes: Sept 1853
Set Post for Qr Section Corner & drove charred stake
built mound with trench

9/8/1978 Dug @ M.H.D iron. Dug 4½' deep to bedrock. Found nothing but bedrock beneath the iron (removed). Found a 10" x 12" x 17" boulder (1' deep and just beneath the old road) over piece of broken glass 1.9 So. and 1.1 East of the M.H.D location. Downed stone and drove a ¾" iron on the NE side and an L-shaped iron on the NW side and set a CIM over the stone. The corner is .8 N of the R/W fence. Set a Survey Marker sign & post 1' East. RP CSD in E side pp# 40374 NNW 6.87

W ¼ Cor Sec 30 Dover 106-11 #613006 (3)

E. ¼ Cor. Sec. 25 Eyota 106-12

Gov. Notes 1853 Oct. B all, Dep. Sur.
North between 25 and 30.
40.00 Set quarter section post.
Drove charred stake.