Pat with Dover

9-20-73 set C/M over lowered mon. found. cut 3-7⁵

Section Corner Township corner

SW 31 ① Dover 106-11
SE 36 Egypt 106-12
NE 1 Orion 105-12
NW 6 Elmira 105-11

#613105

No known records of corner ever having been found - assum Hunter set monument in 1888 or thereabouts

- Govt notes - set post 50 chs north of section corner

10" burr oak S 61½° E 195 lks = 128.7
10" burr oak N 48½° E 370 lks = 224.2

scrub 1st rate, gently rolling scattered oaks

9-20-73 dug in center crossroads without line or mear - found original monument leaning nearly flat toward SW with top very rounded showing corner may have been exposed to road traffic many years

found quite definate place where base of monument had originally rested. lowered stone and placed C I N on top with a medium sized boulder on N side this boulder found with wood hub near corner stone.

51.4 N W to Cone nail on S B side P P ± 1859

57.48 N W to punch hole in top center west end gale culvert large road culvert

59.85 N E to same east end

67.75 N E to appox top center 8" spiral grooved gale. tile vent of some kind, 3' above ground.

#613105 (2)

SW SEC COR 31 TWP CORNER DOVER 106-11
NW SEC COR 6 ELMIRA 105-11
NE SEC COR 1 ORION 105-12
S.E. Cor. Sec. 36 Twp. Corner Eyota 106-12

Gov. Notes-Ball, Dep. Sur. 1853, Oct.
North between 1 and 6.
80.00 Set post.
Br. Oak 10 in. S-61½ E-195 lks.
Br . Oak 10 in. N-48½ E-370 lks.

6-1996 Roger Brand reports top section of CIM broken off.

7-31-96 Found CIM with broken off Head down 12" to + on monument the corner falls 1' west of ℄ ~~Cheek~~ CR # 136 & 3' North of Ave ℄ 60th St SE ℄+W CSD in P.P # 51082 NW 51.80