10-17-75 St CIM #613106. (1)

1/4 corner West 1/4 31 Dove 106-11
9-21-73 East 1/4 36 Eyota 106-12
No records or any knowledge or witness trees set transit on high place between township corner and center road near center intersection of Co H road # 129 Town line being Co road # 136 ℄ road at above corner Came on this line or very little west dug entire area to 5 foot depth found road fill dug but not to clean clay - found lone stone boulder shaped like clam shell 6 x 11 x 16 lying nearly but not completely flat down over 4'- nothing but wood from road fill in area

over

"Created" corner near stone which came in center
the road intersection and range line as near as possible
without establishing NW corner 3/ Dover.
- set ported stone found we lead with 2 x 10 x 13
limestone on east side and 18" ϕ old rotted log
on S side stone, Top stone down 4' ±. corner
suggested as possible until proven otherwise
no trees ϕ any kind, no trees any direction.

36.0 N E to Cone nail on N W side tele pole

104.2 W N W to Cone nail on N side tele pole

958
1/5
959
1
8 yone

Gov't notes: Sept 1853
Set Post for 9. sec Cor
B.T's Burr Oak 5" S 6½° E 520 links
Burr Oak 10" N 85° W 554 "

#6131060 (2)

W ¼ Cor 31	Dover	106-11
E ¼ Cor 36	Eyota	106-12

10-7-75 Dug ⅓ x 9 x 5 deep to cover M&L location but found nothing

10-17-75 Remeasured the E. line of Section 36 and reset the corner M&L at 2637.10'
Set C.I.M. over a ½" x 18" iron rod. Corner lies 2.5' West ℄ of N-S twp road and 5' North ℄ road west.

R.P.'s

CSD NW side telephone pole NE 32.15
CSD SW side telephone pole NW 100.35

W 1/4 COR 31 DOVER 106-11 #613106 (3)
E. ¼ Cor. Sec. 36 Eyota 106-12

Gov. Notes 1853 Oct. Ball, Dep. Sur.
North between 31 and 36.
40.00 Set corner post.
Br. Oak 5 in. S6½E 520 lks.
Br. Oak 10 in. N85W 554 lks.