6-14-76 Dug down - found stake hole - set #1
a 1¼" x 15" pipe at road surface

5-19-82 CIC/P² 9-20-95 CHO SET 1" SR PIPE W/CAP

¼ Corner south ¼ 32 Dover 106-11

North ¼ 5 Elmira 105-11.

#613204

No records.

1939 Co Hwy Dept Book 101.

found stone - hub reset.

spike power pole. (brace) N W 33.1.

" " " S W 42.7.

1939 B 101 P 75. Hub over stone mon.

Sta 2+84.5 a PI on (10) .00 likely P.T.

1935 B 75 P 7. found old wood stake in pile flat L stones
set large nail on west side stake.

Maple Ave SE 43.0

1935 Co H & D BB3 Pl. found old stake in elm pile at survey stake over corner.
Sp in brace pole N W 33.1 Sp in P.P. SW. 42.7
Mean south to 1/4 5-8- 5282.7

Gov'T notes. 1853 Set Post for Gr See Corner
B.T.'s Black Oak 10" N 70°E 313 links (1866)
Black oak 8" S 78°E 278 " (1835)

9-27-1972 Co H.D

Found 2 x 2 hub above 1' long spike which runs above a 2" x 3" x 18" oak stake 5' below ground
Set 60p spike
Spk & disc in P.P. — North 44.98
PP NE 63.40

#613204 # 2

1/4 cor.	South 1/4 32	Dover	106-11
	North 1/4 5	Elmira	105-11

6-14-76 Dug down + found a very definite stake hole with limestone piled around as found by C.H.D in 1972. Drove a 1¼" x ~~5~~ 32" pipe in the stake hole + placed a ½" rod in top of pipe Set a 1¼" x 15" pipe at the road surface

Corner falls 2' west of the fence North + on the N edge of C.R. # 32 at present time

R.P.'s

C.H dept disc in P.P. (E side)	45.00 N.N.E.	45.06
C.H. dept disc in P.P. # 1969	05.25 N.E.	63 43
C.S disc in P.P. # 922	W.N.W.	221.83

Punch hole in top E. end 18" C.M.P. 21.96 N.N.E. 21.93
Punch hole in top W. end 18" C.M.P. 35.11 N.W. 35.08

8-8-77 Tied corner for road grading. Set RR spike
West 121.79 in ℄ road West and on line to
RR spike W 266.52 in ℄ road West

5-19-82, S. 1/4 Cor 32: Found 1"1/4" pipe set 6-14-76.
Removed the pipe and set a CTC/pc and checked
close RP's:
CHD Disc in East side pp NNE 45.03
CHD Disc in pp #1969 NE 63.33
Punch hole in top E. end 18" CMP NNE 21.96
Punch hole in top W. end 18" CMP NW 35.11

1/4 CORNER SOUTH 1/4 32 DOVER 106-11 (3)
NORTH 1/4 5 ELMIRA 105-11 #G13204

6-16-95 - FOUND CIC/P². SET 1" SQ PIPE W/CAP ON BACK SLOPE OF CURVE NE OF CORNER. ℄ CR#32 SSW 52'.
LINE OF P.P.'s RUNNING NORTH WEST 14'.
T @ REF PIPE
4 RT P.K NAIL IN 1ST P.P. SOUTH OF CR#32 TO SOUTH 1/4 32

20° 56' 28" dh 02	19° 16' 29" dh 02
3° 13' 26" dh 03	1° 33' 32" dh 04
17° 43' 02"	17° 42' 57"

TO 5 1/4 COR 32 (CIC/P²)
VA 89° 33' 19" dv 07
SLOPE 42.25 HOR 42.245

9-20-95 - CHD SET 1" SQ PIPE W/CAP.