#613404

/

¼ corner south ¼ 34 Dover 106-11
north ¼ 3 Elmira 105-11

4-1892 Chas Fraser P 483 No 460 & 3 John Ricketer

Corner gone, set temp point N & L 40.03 ¼ 2642.14.
which came in "about" line of fence running south,
used above corner to set center section 3 by intero
lines - no meas - no bearings.

Gov't notes: 1853 - Set Post & drove shaved stake for ¼ Corner, Built mound & trench

10-17&18-1979 Dug here with the backhoe from the traverse nail East 5', West 3', North 7', South 6½' by 2½' deep to clay. We measured from So. 33-34 to the S¼ Cor 35 and T. Fraser's prorated location would have been 3.90 North and 1.25 East of the t.n Conditions here were poor, the old road being very close to clay. We did find some charcoal in the clay 4.5 North and 1.0 E. of the t.n We could not prove this was a chained stake but it was concentrated in an area of about 4 or 5" diam. (The Govt Notes call for a chained stake at this corner) Someone had dug here previously, then dig centered about 2' West of our t.n and extending So. 4', North 5', and being now 3' wide. The line of the fence North here is difficult to determine and this dig could have been centered on it.

(613404) C 11-23-98
MWD EA

N ¼ 3 105-11 Elmira

S ¼ 34 106-11 Dover

Set CIM over 5/8" rerod midway and on line between Section Corners. The Corner Falls 3' North of ℄ 60th St. Twp Rd. & 1½' East of Center old fence Ridge North

CSD in P.P. (No Number) North 27.80

Trav. Pt OLIVE (1" sq. pipe w/Cap WNW 192.64